

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

JUL 29 2009

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE – Other instructions on page 2.		5. Lease Serial No LCO 67132
1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		6. If Indian, Allottee or Tribe Name
2. Name of Operator C.O.G. OPERATING		7. If Unit of CA/Agreement, Name and/or No
3a. Address 550 W TEXAS, STE 1300 MIDLAND, TX 79701	3b. Phone No (include area code) 432.686.3021	8. Well Name and No. DENTON FED #6
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1880' FSL 2080 FWL SEC 22, T18S, R29E		9. API Well No. 30-015-24135
		10. Field and Pool or Exploratory Area TURKEY TRACK, 7 RIVERS, PN,GB,SA
		11. Country or Parish, State EDDY CO., NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

5/13/09 MIRU. Rig up swivel & start drilling.
5/14/09 Drill to 289'.
5/15/09 Drill from 289' to 745'. Started losing fluid while drill @ 418'. Flowing water when not pumping.
5/16/09 Open well up, flowing water.
5/18/09 Drill from 745' to 978'.
5/19/09 Start drill @ 978', fell out of cement @ 1,040'. Ran tbg to 1,075'. Circ. well clean. PooH tbg. Lay down D.C. TiH w/ PKR to 450'. Test csg from 450' to 1,075' @ 1000 psi. Found water flow @ 418'. PooH PKR.
5/20/09 OK w/ BLM Jim Amos to set 15sx cmt plug @ 1,050'. Calc. TOC @ 900'. PooH. Pick up 4 1/2" PKR, go in hole to 210'. Sqz 250sx cmt @ 2 bpm @ 500 psi. S.I. @ 200# & falling to 0 psi. Attempt to hesitate sqz. Pressure falls to 0 psi. S.I. for 24 hrs.
5/21/09 Pressure test sqz - 1500 psi. Bleed off pressure & monitor well.
5/22/09 Release & PooH w/ PKR. TiH & Tag TOC @ 264'. Lay down tbg. Fill well w/ water. S.I.
5/26/09 Monitor well. 0 bubble 4 1/2 x 4 1/2 x 8 5/8. Richard Carrasco witness, OK to spot plug 264' to surface, WOC O.N. Tag TOC.
5/27/09 @ 16' dig out W.H. to 10', cut off 4 1/2 & 8 5/8 csg. Monitor well, no leaks. Install DH marker w/ vent hole on top. OK by Richard Carrasco NM BLM.

Approved as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

APPROVED

JUL 24 2009

JAMES A. AMOS
SUPERVISOR-EPS

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
GARY EGGLESTON

Title P&A Supervisor

Signature

Date 06/09/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)