Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTE	i

AUG 12 2009

ease Serial No

064200

FORM APPROVED	
OMB NO 1004-0135	
entree January 21, 2004	

abandoned well. Use Form	o if indian, Anottee of The Name	
SUBMIT IN TRIPLICATE - (7 If Unit or CA/Agreement, Name and/or No	
1 Type of Well Oil Well Gas Well X Other 2 Name of Operator		SWD 8. Well Name and No PENNZOIL 10 FED. #2 SWD
CIMAREX ENERGY CO. OF COLORADO 3a Address 5215 N. O'CONNOR BLVD., STE. 1500,	ATTN: ZENO FARRIS 3b Phone No. (<i>include area</i> 1RVING, TX 75039 972.443.6489	9. API Well No. 30–015–22326 10 Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey I 1,980' FSL & 660' FWL SECTION 10, T-24S, R-26E	Description)	BLACK RIVER 11. County or Parish, State EDDY NM
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NO	OTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE	OF ACTION
Notice of Intent X Subsequent Report • Final Abandonment Notice	Acidize Deepen Alter Casing Fracture Treat Casing Repair New Construction Change Plans X Plug and Abandon Convert to Injection Plug Back	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete Other Temporarily Abandon Water Disposal
		date of any proposed work and approximate duration thereof red and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection)

07/02/09: SET 5-1/2" CIBP @ 7,540'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF CIBP; CIRC. WELL W/ PXA MUD; MIX & PUMP A 25 SX. CMT. PLUG @ 5,559'; WOC & TAG TOP OF CMT. PLUG @ 5,315'.

07/06-07/09: CUT & PULL 5-1/2" CSG. @ 4,491'.

07/08/09: MIX & FUMP A 40 SX. CMT. FLUG @ 4,550'; WCC & TAG CMT. FLUG @ 4,400'; MIX & FUMP A 40 SX. CMT. PLUG @ 1,350'; WOC & TAG TOP OF CMT. PLUG @ 1,193'.

07/09/09: PERF. 8-5/8" CASING @ 650'; MIX & SQZ. AN 80 SX. CMT. PLUG @ 650'; WOC & TAG TOP OF CMT. PLUG @ 425'; PERF. 8-5/8" CSG. @ 60'; MIX & CIRC. TO SURFACE A 65 SX. CMT. PLUG @ 60'-3'; DIG OUT & CUT OFF WELLHEAD 3' B.G.L. & WELD ON STEEL PLATE & DRY HOLE MARKER.

WELL PLUGGED AND ABANDONED 07/09/09.

Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.

		prof. Act States and gr. marks
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title	ACCEPTED FOR RECORD
_DAVID A. EYLER deyler@milagro-res.com	AGENT	L'OOCH LED LON MEDOND
Danoth. Se	Date 07/29/09	
THIS SPACE FOR FEDER	AL OR STATE OFFICE US	E AUG 9 2009
Approved by	Title	DER
Conditions of approval, if any, are attached. Approval of this notice does not warracertify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon	unt or Office lease	BUREAU OF LAND MANAGEMENT
Title 18 II S.C. Section 1001, and Title 43 II S.C. Section 1212, makes it a crime for	r any person knowingly and willful	y to prove to any department or agency of the United