Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised May 08, 2003 WELL API NO.	3
1625 N. French Dr., Hobbs, NM 88240 District II		30-015-22545		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE		
District IV Santa Fe, NW 8/303		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			L-490	
•	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	•
(DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLICE"			Mobil 21 State	-
PROPOSALS.)	, , , , , , , , , , , , , , , , , , ,			\dashv
1. Type of Well:		RECEIVED	8. Well Number 2	
Oil Well Gas Well	Other	050 0 0 0000		_
2. Name of Operator Toyas I	ndependent Exploration, In	DEC 2 6 7003	9. OGRID Number	
	• • • • • • • • • • • • • • • • • • • •		22596	4
3. Address of Operator 1600 S	mith, Suite 3800 Housto	n, TX 77002	10. Pool name or Wildcat WildcatWolfcamp	
4. Well Location				\dashv
	1000		1000 Wood	
Unit Letter K :	1980 feet from the South	n line and	1980 feet from the West line	1
Section 21	Township 23S Ra	ange 27E	NMPM Eddy County	- [
Section 21	11. Elevation (Show whether DR			228
	3162' GR	, KKD, KI, OK, etc.,		
12. Check A	Appropriate Box to Indicate N	ature of Notice	Report or Other Data	æ.e:
NOTICE OF IN			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		1
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DD	LLING OPNS PLUG AND	, I
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ND	
	COMPLETION	CEMENT JOB		
OTHER:		OTHER:]
			and give pertinent dates, including estimated	
	ork). SEE RULE 1103. For Multip	le Completions: At	tach wellbore diagram of proposed completic	on
or recompletion.				
12/09/03 through 12/12/09	3			
MIDLI Mass Moll Comiss		ation from Davis	America NINACOD Antonio Office NID	
			Arrant, NMOCD, Artesia Office. ND se packer and TOH w/ tbg. MIRU	
			to 11,200'. Set Alpha 10K CIBP at	
			ins loaded 2 JSPF on 60 Deg phasing.	
	4 holes, 0.41" EHD. 32 gr char			
TIH w/ 2 3/8" X 5.50" Arro	wset 1X pkr w/ T2 on/off tool w/	1.81" "F" profile n	nipple. Set packer at 9586' w/ 12K	
compression. ND BOP,	NU Tree. Open up well and star	rted flowing. Flow	100 mcf/d. RU BJ Services and	
			Flow test well. 24 hr potential 00 psi on 32/64 choke. Rig down and	
	EW PBTD11,140'. NEW RES			
2				
I hereby certify that the information	1 2 1 1 1 1	4 - 6 - 1 - 1 - 1	11.17.6	
	above is true and complete to the b	est of my knowledg	e and belief.	
SIGNATURE / Ome o	Kec TITLE	Agent	DATE_11/12/03	
Type or print name Gene Lee			Telephone No. (505) 626-4292	
(Till: C. Citt	FOR RECORDS ONLY		DEC 31	— 204
			DATEDATE	CU[]4
Conditions of approval, if any:				