

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP - 2 2009

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No NMNM11039,

SUNDRY	NOTICE	S AND	REPO	DRTS	ON	WELLS

Do not use thi abandoned we	is form for proposals to drii II. Use form 3160-3 (APD) fo	or to re-enter an or such proposeds	Derater Copy LIVE of If Indian, Allottee	or Tribe Name			
SUBMIT IN TRI	7. If Unit or CA/Agre 3 1 2009	eement, Name and/or No.					
I. Type of Well	8 Well Name and No BRUSHY 12-A F	EDEDAL 1					
Ø Oil Well ☐ Gas Well ☐ Oth		EDERAL I					
2. Name of Operator CHESAPEAKE OPERATING,	INC. E-Mail: linda.good@ch	DA GOOD BY:	9 API Well No. 30-015-25615				
3a Address P.O. BOX 18496 OKLAHOMA CITY, OK 73154	1-0496 Pt	Phone No. (include area co 1: 405-935-4275	10. Field and Pool, of SWD DELAWA	10. Field and Pool, or Exploratory SWD DELAWARE			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	· . ·	11. County or Parish,	and State			
Sec 12 T26S R29E SWNW 20	EDDY COUNT	Y, NM					
12. СНЕСК АРРГ	ROPRIATE BOX(ES) TO IN	DICATE NATURE OF	FNOTICE, REPORT, OR OTHE	R DATA			
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	□ Acidize	Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off			
	Alter Casing		Reclamation	☐ Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	□ Other			
☐ Final Abandonment Notice	Final Abandonment Notice Change Plans		Temporarily Abandon				
	Convert to Injection	Plug Back	☐ Water Disposal uting date of any proposed work and app				
following completion of the involved testing has been completed. Final A determined that the site is ready for f	I operations. If the operation results bandonment Notices shall be filed o final inspection.) JLLY, REQUESTS PERMISSI DAD, RACK AND TALLY J-55	in a multiple completion or nly after all requirements, in ON TO CONVERT THI	BIA. Required subsequent reports shall recompletion in a new interval, a Form 3 cluding reclamation, have been complete S WELL TO A SALT WATER DISSEE ATTACHED FOR CONDITIONS OF AP	1160-4 shall be filed once and the operator has			
3. RIH W/BIT AND SCRAPER AND CHECK PBTD. POH W/BIT. SUBJECT TO LIKE							
4. RIG UP WIRELINE CO. PERFORATE DELAWARE 3,324-44' (20') 4 SPF. APPROVAL BY STATE							
5. RIH W/TREATING PACKEI		ST CASING ABOVE A	LL PERFS TO 500 PSI. A	or order			
14. I hereby certify that the foregoing is	Electronic Submission #7289	77 verified by the BLM W PPERATING, INC., sent t	ell Information System o the Carlsbad				
Name (Printed/Typed) LINDA GC	OOD	Title SR. R	REGULATORY COMPLIANCE SP	EC			
Signature (Electronic S	Submission)	Date 08/05	/2009				
	THIS SPACE FOR F	EDERAL OR STATI	E OFFICE USE				
Approved By		Title	APPROVED	Date			
Conditions of approval, if any are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the sub uct operations thereon.	oject lease Office	AUG 2 5 2009				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crin statements or representations as to a	ne for any person knowingly ny matter within its jurisdict	and willfully to make to any department ion. BUREAU OF LAND MANAGEME CARLSBAD FIELD OFFICE	or agency of the United			

Additional data for EC transaction #72897 that would not fit on the form

32. Additional remarks, continued

- 6. LOWER PACKER DOWN TO 3,275'. ACIDIZE DELAWARE WITH 3,000 GAL 15% NEFE, DROPPING 100 PERF BALLS THROUGHOUT JOB. DISPLACE ACID TO PERFS. SURGE BALLS OFF PERFS. FRAC NEW PERFS DOWN TBG PER FRAC RECOMMENDATION (ANTICIPATE 35,000# SAND). POH W/PACKER.
- 7. RIH W/TREATING PACKER AND RBP. SET RBP @ 3,275' AND PACKER @ 3,150'. ACIDIZE THE UPPER BRUSHY CANYON PERFS WITH 3,000 GAL 15% NEFE ACID. OVER DISPLACE ACID. POH W/RBP & PACKER LAYING DOWN 2 3/8" PRODUCTION TBG.
- 8. RIH W/4 1/2" BAKER LOC-SET PACKER ON 2 3/8" IPC TBG TO 3,200'. LOAD BACK SIDE WITH PACKER FLUID. SET PACKER AND PRESSURE TEST CASING TO 500 PSI.
- 9. ND BOP/NU WH. RD MO. RUN MIT W/OCD. HOOK WELL UP FOR INJECTION.

WELLBORE DIAGRAM AND PROCEDURE ATTACHED.

(CHK PN 891208)

Workover Proposal



BRUSHY 12-A FEDERAL 1

Field:

BRUSHY DRAW DELAWARE

County: EDDY

NEW MEXICO


State: Location:

SEC 12, 26S-29E, 2021 FNL & 630 FWL GL 2,978.50 KB 2,984.50

Elevation:

KB Height: 6.00

Spud Date: 6/14/1987 Initial Compl. Date: API #: 3001525615 CHK Property #: 891208 1st Prod Date: 7/31/1987 PBTD: Lateral 1 - 3468.0 TD: 3,500.0



Page 1/1

Brushy 12-A Federal 1 Eddy County, New Mexico Convert to SWD Procedure

Date: August 4, 2009

Location: 2021' FNL & 630' FWL Sec. 12-T26S-R29E

Casing: 4 ½" 10.5 & 11.6# 0-3,480' ID - 4.000", Drift - 3.875"

PBTD/TD: 3,468'/3,500'

Current Perfs: Delaware (Brushy Canyon) 3,232-44'

Proposed Perfs: Delaware (Brushy Canyon) 3,324-44'

Recommended Procedure:

1. MIRU PU. NU BOP. Unload, rack and tally J-55 2 3/8" IPC tbg.

- POH w/ rods and tubing.
- 3. RIH w/ bit and scraper and check PBTD. POH w/ bit.
- 4. Rig up wireline co. Perforate Delaware 3,324-44' (20') 4 spf.
- 5. RIH w/ treating packer to 3,150°. Pressure test casing above all perfs to 500 psi.
- Lower packer down to 3,275'. Acidize Delaware with 3,000 gal 15% NEFE, dropping 100 perf balls throughout job. Displace acid to perfs. Surge balls off perfs. Frac new perfs down tog per frac recommendation (anticipate 35,000# sand). POH w/ packer.
- 7. RIH w/ treating packer and RBP. Set RBP @ 3,275' and packer @ 3,150'. Acidize the upper Brushy Canyon perfs with 3,000 gal 15% NEFE acid. Over displace acid. POH w/ RBP & packer laying down 2 3/8" production tbg.
- 8. RIH w/ 4 ½" Baker Loc-set packer on 2 3/8" IPC tbg. to 3,200'. Load back side with packer fluid. Set packer and pressure test casing to 500 psi.
- 9. ND BOP/NU WH. RD MO. Run MIT w/ OCD. Hook well up for injection.

Chesapeake Operating, Inc.

NMNM-11039: Brushy 12-A Federal 1

API: 30-015-25615 Sec. 12, T-26-S, R-29-E

RE: Complete as disposal well, Conditions of Approval

- 1. BOP installed should be a 5M. It will be installed and tested according to regulation and manufacturer recommendations.
- 2. Produced water to be disposed must come from the same lease, unless prior approval is given.
- 3. This agency shall be notified of any change in your method or location of disposal.
- 4. Compliance with all provisions of Onshore Order No. 7.
- 5. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 6. This agency reserves the right to modify or rescind approval whenever it determines continued use of the approved method may adversely affect the surface or subsurface environments.
- 7. All above ground structures on the lease shall be painted Juniper Green, Federal Standard 595a-34127, within 90 days, if you have not already done so.
- 8. Any on-lease open top storage tanks shall be covered with a wire screen to prevent entry by birds and other wildlife.
- 9. This approval should not constitute the granting of any right-of-way or construction rights not granted by the lease instrument.
- 10. If water is transported via a pipeline that extends beyond the lease boundary, then you need to submit within 30 days an application for right-of-way approval to the Realty Section in this office if you have not already done so.

DHW 082509