RECEIVED OCT 0 2 2009

Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		June 19, 2008 WELL API NO.
District II	OIL CONSERVATION DIVISION		30-015-31552
1301 W Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rto Brazos Rd, Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-5862
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name AID 24P State
PROPOSALS.) 1. Type of Well: Oil Well X	Type of Well: Oil Well X Gas Well Other		8. Well Number 23
2. Name of Operator		9. OGRID Number	
Lime Rock Resources A, L.P. 3. Address of Operator			255333 10. Pool name or Wildcat
Heritage Plaza, 1111 Bagby St. Suite 4600, Houston, TX 77002			San Adres/Yeso
4. Well Location			
Unit Letter: K: 1,860 feet from the South line and 1,650 feet from the West line			
Section 24 Township 17S Range 28E			NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,697' GR			
5,097 OK			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
TEMPORARILY ABANDON X	CHANGE PLANS COMMENCE DRIL		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Current Condition:			
8-5/8", 24#, J-55 Casing set @ 639'. Cemented with 550 sxs to surface.			
5-1/2", 15.5#, K-55 Casing set @ 4,237'. Cemented with 745 sxs to surface.			
Perfs: 2,596-3,197'			
Temporarily Abandon well as follows: Pull rods, pump, and tubing. Set CIBP @ 2,550'. Place 35' cement on top of plug. Circulate casing with salt water and test to 500#. Install			
tubing sub and valve. Work should be performed as soon as OCD approval is received.			
I hereby certify that the information	above is true and complete to the b	est of my knowledge	and belief.
12 /	Un:11		
SIGNATURE .	TITLE Vice I	President – Operation	ns DATE 10/10/2009
Type or print name <u>C. Tim Miller</u> For State Use Only			
APPROVED BY: Putters Conditions of Approval (if any):	o livius title Co	mfchares D	GALER DATE 10/14/09

Sec 24-17S-28E Eddy County, NM

TD @ 4,280'