REGENVED FEB 2 2 2010

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA SUNDRY NOTICES AND REPORTS ON WELLS

FORM A	PPROVEI
OMB No	1004- 013

Expires July 31, 2010 5. Lease Serial No SHL: NM115413

OOD ADTECIAL SOUTH NO.	ICES AND REPORTS ON	
	rm for proposals to drill or to I se Form 3160-3 (APD) for such	
	E - Other Instructions on pag	
1 Type of Well		8 Well Name and No
Other Gas Well Other Name of Operator		White Federal Com #1H
Marbob Energy Corporation		9 API Well No.
3a. Address	3b Phone No (nclude area code) 30-015-36185
P.O. Box 227 Artesia, NM 88211-0227	575	-748-3303 To Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T, R, M., or Surve	ey Description) Lat.	Willow Lake; Bone Spring, SE
480' FNL & 380' FEL, Unit A (NE)	VE) Long.	11. County or Parish, State
Sec 21-T25S-R29E		Eddy NM
	(S) TO INDICATE NATURE	OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION
Notice of Intent Acidiz	Deepen Deepen	Production (Start/ Resume) Water Shut-off
Altern	ng Casing Fracture Treat	Reclamation Well Integrity
X Subsequent Report Casing	Repair New Construction	Recomplete X Other
Chang	e Plans Plug and abandon	Temporarily Abandon Completion Operations
Final Abandonment Notice Conve	rt to Injection Plug back	Water Disposal
1/4/10 to 1/5/10 MIRU WSU. Tag	DVT & drill out.	
1/4/10 to 1/5/10 MIRIJ WSI 1 Tag		
•	DVT & drill out.	732).
1/6/10 Perforate Bone Spring 1097:	DVT & drill out. 5', 11125', 11275', & 11425' ((32). 100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431	DVT & drill out. 5', 11125', 11275', & 11425' (9 gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A	
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per	DVT & drill out. 5', 11125', 11275', & 11425' (9 gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91	100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Perforac w/382588# sand & 402820 gal	DVT & drill out. 5', 11125', 11275', & 11425' (9 gal 7 1/2% NEFE. Frac w/2 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110.	100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Perforac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75	100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% IR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring E. Frac w/376426# sand & 406548 gal fluid. ISIP 187 175', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1	100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% IR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring E. Frac w/376426# sand & 406548 gal fluid. ISIP 187 175', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal
1/6/10 Perforate Bone Spring 10973 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Pe NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Perforac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean.	100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% IR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring E. Frac w/376426# sand & 406548 gal fluid. ISIP 187 175', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal
1/6/10 Perforate Bone Spring 1097: 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all frac/2/2/10 Set 208 jts 2 7/8" J-55 tubing	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'.	10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% IR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring E. Frac w/376426# sand & 406548 gal fluid. ISIP 187 (375', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal 566#, AIR 119 BPM.
1/6/10 Perforate Bone Spring 10975 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all frac 2/2/10 Set 208 jts 2 7/8" J-55 tubing	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'.	10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% IR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF7 BPM. Set frac plug @ 8933'. Perforate Bone Spring E. Frac w/376426# sand & 406548 gal fluid. ISIP 1875', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal 7 1/2% NEF7 BPM.
1/6/10 Perforate Bone Spring 1097: 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all frac 2/2/10 Set 208 jts 2 7/8" J-55 tubing 14 1 hereby certify that the foregoing is true and correct Name (Printed/Typed) Stormi Davis	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'.	## 100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. ### 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF ### 7 BPM. Set frac plug @ 8933'. Perforate Bone Spring ### 88 Frac w/376426# sand & 406548 gal fluid. ISIP 187 ### 1575', 7725', 7875', 8025' & 8173' (40). Acdz w/3500 gal ### 158
1/6/10 Perforate Bone Spring 1097: 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all fr 2/2/10 Set 208 jts 2 7/8" J-55 tubing 14 1 hereby certify that the foregoing is true and correct Name (Printed/Typed) Stormi Davis	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'. Title Pi	## 100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. ### 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF
1/6/10 Perforate Bone Spring 1097: 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all fr 2/2/10 Set 208 jts 2 7/8" J-55 tubing 14 1 hereby certify that the foregoing is true and correct Name (Printed/Typed) Stormi Davis	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75 d & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'.	## 100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. ### 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF
1/6/10 Perforate Bone Spring 1097: 1/12/10 Acdz 10975-11425' w/2500 1/13/10 Set frac plug @ 10828'. Per NEFE. Frac w/363819# sand & 431 Spring 9675', 9825', 9975' & 10125' ISIP 1649#AIR 105 BPM. 1/14/10 Set frac plug @ 9560'. Per Frac w/382588# sand & 402820 gal 8375', 8525', 8675' & 8825' (32). A AIR 112 BPM. Set frac plug @ 828 7 1/2% NEFE. Frac w/414292# san 1/25/10 to 1/30/10 Drilled out all fr 2/2/10 Set 208 jts 2 7/8" J-55 tubing 14 1 hereby certify that the foregoing is true and correct Name (Printed/Typed) Stormi Davis	DVT & drill out. 5', 11125', 11275', & 11425' (2) gal 7 1/2% NEFE. Frac w/4 rforate Bone Spring 10325', 500 gal fluid. ISIP 1734#, A (32). Acdz w/2500 gal 7 1/2 forate Bone Spring 9025', 91' fluid. ISIP 1593#, AIR 110. cdz w/3500 gal 7 1/2% NEFI 8'. Perforate Bone Spring 75'd & 485202 gal fluid. ISIP 1 ac plugs. Circulate clean. g & packer @ 6728'. Title Pinate 2/	## 100068# sand & 406411 gal fluid. ISIP 1110#, AIR 68 10475', 10625' & 10775' (32). Acdz w/2500 gal 7 1/2% AIR 108 BPM. Set frac plug @ 10211'. Perforate Bone 2% NEFE. Frac w/ 381569# sand & 406039 gal fluid. ### 75', 9325', & 9475' (32). Acdz w/2500 gal 7 1/2% NEF

States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction (Instructions on page 2)