

OCD-ARTESIA

RECEIVED

MAR 16 2010

NMOCD ARTESIA

Form 3160-5  
(April 2004)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

5. Lease Serial No.

LC 067132

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No

Denton Fed. #3

9. API Well No.

30-015-23823

10. Field and Pool, or Exploratory Area

Turkey Track

11. County or Parish, State

Eddy

**SUBMIT IN TRIPLICATE- Other instructions on reverse side.**

1. Type of Well

☒ Oil Well☐ Gas Well☐ Other

2. Name of Operator

COG OPERATING

3a. Address

550 W. Texas ste1300, Midland, TX 79701

3b. Phone No. (include area code)

432-686-3021

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC 27 18S 29E 1980 FNL 1980 FWL

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

## TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

## 2-16-10 Notify BLM Move In

2-16-10 1. Set 4 1/2 CIBP @ 1970'

2-17-10 2. Tubing @ 1970' Circulate well w/10# MLF. Cap CIBP w/ 25sx C Cement. 1970-1608 Cal. TOC.

2-17-10 3. Tubing @ 1165'. Spot 25sx C cement 2% CAC. OC-4hrs no tag

2-17-10 4. Tubing @ 1165' Re-spot 25sx C cement WOC-overnight Tag Plug @ 750'

2-18-10 5. Tubing @ 750' Spot 15sx C cement 750-533 Cal. TOC

2-18-10 6. Perf @ 475' Packer @ 32' Squeeze 150sx C cement. WOC overnight. Tag Plug @ 180'

2-19-10 7. Perf @ 170' &amp; 60' Packer @ 32' pump 35sx C Cement down 4 1/2 &amp; out 8 5/8 to Surface

POOH tubing. Top off well bore. \*bottom of tubing @ 160'

Accepted as to plugging of the well bore.  
Liability under bond is retained until  
Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Signature

Title

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

MAR 12 2010

BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

3/17/2010