

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br>30-015-02302  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br>CONNIE C STATE  |
| 8. Well Number # 17   |
| 9. OGRID Number   |
| 10. Pool name or Wildcat  |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
NEW MEXICO OCD FOR YESO ENERGY

3. Address of Operator

4. Well Location

Unit Letter: D : 660 feet from the N line and 660 feet from the W line  
Section 25 Township 19S Range 28E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH AND SET 5 1/2" CIBP @ 1764' - TOP WITH 25 SACKS - CIRCULATE PLUGGING MUD
2. SPOT 25 SACKS @ 1370' - WOC - TAG
3. 25 SACKS @ 874' - TAG
4. CIRCULATE 15 SACKS FROM 60' TO SURFACE
5. INSTALL DRY HOLE MARKER AND CLEAN UP LOCATION

Notify OCD 24 hrs. prior  
To any work done.

STEEL PITS WILL BE USED FOR THIS PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mark H. Hahn TITLE agent for ocd DATE 4/1/10

Type or print name  
For State Use Only


E-mail address:

Telephone No.

APPROVED BY: Mark H. Hahn TITLE Approval Granted primary well  
Conditions of Approval (if any): is complete by 7/8/2010 DATE 7/8/2010

**Well Name**  
**API #30-015-02302**  
**CONNIE C STATE # 17**

4/6/2010



15 SX @ 60' TO SURFACE'

25 SX @ 874'  
Surface Casing @ 824'

25 SX @ 1370'

CIBP: @ 1764' W/ 25 SX ON TOP

PERFS: @ 1814' TO 1985'  
4 1/2" CASING @ 2075

Hole TD: 2075

Company Name: OCD FOR YESO ENERGY  
LEASE: CONNIE C STATE # 17