

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103 *RA*
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-015-37424
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Marbob Energy Corporation		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 227, Artesia, NM 88211-0227		7. Lease Name or Unit Agreement Name SRO State Unit Com
4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>East</u> line Section <u>16</u> Township <u>26S</u> Range <u>28E</u> NMPM Eddy County		8. Well Number 4H
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3036' GR		9. OGRID Number 14049
		10. Pool name or Wildcat WC; Bone Spring

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Completion Operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/26/10 MIRU.

3/2/10 Drill out DVT. Circulate. Tag PBTD @ 11317'.

3/5/10 Perforate Bone Spring 10838', 11002', 11136' & 11300' (32).

3/22/10 Acdz 10838-11300' w/1500 gal 10% NEFE. Frac w/346076# sand & 319948 gal fluid. ISIP 1020#, MXTP 7081#, AIR 106.7 BPM. Set CFP @ 10741'. Perforate Bone Spring 10200', 10350', 10500' & 10650' (32). Acdz w/1500 gal 10% NEFE. Frac w/342679# sand & 316688 gal fluid. ISIP 1158#, MXTP 6594#, AIR 112.3 BPM. Set CFP @ 10088'. Perforate Bone Spring 9550', 9700', 9850' & 10000' (32). Acdz w/1500 gal 10% NEFE. Frac w/336150# sand & 311597 gal fluid. ISIP 1228#, MXTP 7031#, AIR 112 BPM. Set CFP @ 9465'. Perforate Bone Spring 8900', 9050', 9200' & 9350'. Acdz w/1500 gal 10% NEFE. Frac w/342565# sand & 322374 gal fluid. ISIP 1160#, MXTP 6728#, AIR 118 BPM.

3/23/10 Set CFP @ 8808'. Perforate Bone Spring 8250', 8400, 8550' & 8700' (32). Acdz w/1500 gal 10% NEFE. Frac w/356092# sand & 313432 gal fluid. ISIP 1132#, MXTP 6442#, AIR 116 BPM. Set CFP @ 8162'. Perforate Bone Spring 7600', 7750', 7900' & 8050' (32). Acdz w/1500 gal 10% NEFE. Frac w/357409# sand & 319896 gal fluid. ISIP 1230#, MXTP 5939#, AIR 114.5 BPM. Set CFP @ 7522'. Perforate Bone Spring 6950', 7100', 7250' & 7400'.

3/24/10 Acdz 6950-7400' w/1900 gal 10% NEFE. Frac w/399251# sand & 342257 gal fluid. ISIP 1440#, MXTP 5673#, AIR 113.7 BPM.

3/25/10 Drill out CFP's @ 7522', 8162', 8808', 9465', 10088' & 10741'. Circulate.

4/6/10 Set 185 jts 2 7/8" 6.5# J-55 tubing @ 6191'. Set 5 1/2" 10K ASI-X packer @ 6184'. Place well on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE: Production Assistant DATE: 4/16/10

Type or print name: Stormi Davis E-mail address: sdavis@marbob.com PHONE: (575) 748-3303

For State Use Only

APPROVED BY: Donald May TITLE Field Supervisor DATE 4-28-10
Conditions of Approval (if any):