

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103 *RM*
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-015-20548
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SandRidge Exploration and Production, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 123 Robert S. Kerr Ave, Oklahoma City, OK 73102		7. Lease Name or Unit Agreement Name Skelly
4. Well Location Unit Letter <u>I</u> : <u>1980</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>14</u> Township <u>17S</u> Range <u>31E</u> NMPM County <u>Eddy</u>		8. Well Number <u>111</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3922' DF		9. OGRID Number <u>8041</u>
		10. Pool name or Wildcat Grayburg Jackson 7R VS QN GB SA

RECEIVED
MAY 04 2010
NMOCD ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☒

OTHER: Add Perfs ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/17/10 MIRU.

2/18/10 Clean paraffin out of tbq. POH w/rods & pump. ND WH. NUBOP. POH w/tbg. RIH w/ CIBP & set @ 3300'. Dump 2 sx cmt on top.

2/19/10 RU & perf @ 2300-2575' w/2 spf (105 holes). RD. Hydrotest pkr & 2 7/8 tbg to 6000 psi. RD. RU & spot 250 gals 15% NEFE across perfs. Set pkr @ 2198. Pump 2750 gals 15% NEFE acid. ISP-1530 psi. 15 mins 1470 psi. RD.

2/20/10 Swab well.

2/22/10 Swab well.

2/23/10 Release pkr & LD. LD tbg. RIH w/3-1/2" PH6 tbg & hydrotest to 7000 psi.

Please see attached page.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Terri Statthem* TITLE Regulatory Manager DATE 5/3/10

Type or print name Terri Statthem E-mail address: tstatthem@sdrge.com PHONE: 405-429-5682

For State Use Only

APPROVED BY: *David Gray* TITLE Field supervisor DATE 5-4-2010

Conditions of Approval (if any):

submit sundry including tbg detail - wt., grade, # of joints

2/24/10 Finish RIH w/tbg. RD testers. Set pkr @ 2176.

2/25/10 Fill frac tanks.

2/27/10 Frac w/105800# 16/30 mesh sand. ISIP- 1682 psi. 15 mins-1570 psi. RD.

3/2/10 Open well on 16/64 CK.

3/5/10 Release pkr. POH & LD 3-1/2" tbg & pkr.

3/9/10 RIH w/ 2-7/8 tbg & set @ 2181'. RIH w/rod & pump.

3/15/10 Test: 0 BO, 13 MCF, 59 BW-24 hours.
