OCD-ARTESIA

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAY 2 3 2010

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

	2.42.00
MOCD	/ 57 Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

6 If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

1 Type of Well Oil Well	Gas Well Other	•		8. Well Name and No.		
2 Name of Operator Merit Energy Company		Shugart West 19 Federal #9 9 API Well No.				
3a Address 13727 Noel Rd. Suite 500 Dall	3b Phone No (include area code) ite 500 Dallas, Texas 75240 972-628-1569		area code)	30-015-30924 10. Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec, T., R, M, or Survey Description)		Shugart; Bonespring, North 11. County or Parish, State Eddy Co., New Mexico				
2310' FSL & 2310' FEL Sec. 19-T18S-R31E						
12. CHECK A	PPROPRIATE BOX(ES)	TO INDICATE NATUR	E OF NOLICE,	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (S Reclamation Recomplete Temporarily	Well Integrity ✓ Other Add perfs Abandon		

- Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1. MIRU WSU. ND WH. NU BOP's & test. RU tbg. tools. Kill will if needed w/2% KCL. POOH w/rods, pump & tbg

2. RIH w/bit & scraper to PBTD. POOH. Clean-out fill if needed.

3. RUEL & PU perf gun loaded 3 spf. Assembly to include GR/CCL tools. Log gun on dept & perf Bone Springs 8424-8279' MD. Tie-in using log dated 11/09/2000. Leave well SI while perforating. POOH w/guns. RD EL.

4. MIRU pumping services.

- 5. RIH w/tbg. plug & pkr. Set plug below new perfs. Set pkr above lower perfs (8235'). Pump 5000 gals 15% HCL. Flush w/2% KCL.
- 6. Unseat pkr., retrieve plug & reset plug in window (8230' 8240') and reset pkr above top perfs. Pump 3000 gals 15% NEFE HCL. Flush w/2% KCL. RD pumping service. Swab back acid.

7. Unseat pkr. Retrieve plug & POOH.

8. RIH w/production tbg., rods & pump and hang-off. RDMO WSU. Place well on production and obtain test.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1					
Lynne Moon	Title Regulatory Manager					
Signature Lipu Non	Date	05/03	05/03/2010			
THIS SPACE FOR FEDERAL	OR STATE O	FICE U	朝PPROVFD			
Approved by Approved by	Title		Date	7		
Conditions of approval, if any are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon	office Office		MAY 2 1 2010 Dustin Winkle			
Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person knowingly and r within its jurisdiction	willfu gure r CA	REOF TAMEMANAGEN	PENY of the	United	
(Instructions on page 2)		· · · · · · · · · · · · · · · · · · ·			8	



Merit Energy Company NM-067896: Shugart West 19 Federal #9 API: 30-015-30924

Eddy County, New Mexico

RE: Perf and Acidize NOI – Conditions of Approval

There is to be no surface disturbance beyond the existing pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

3M BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

Submit subsequent report with updated wellbore schematic and well test once work is completed.

DHW 052110