Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

☐ Water Disposal

☐ Temporarily Abandon

FORM APPROVED

~~		55-ri-eace Ser	ial No
			Expires: July 31, 20
AY 2	6	2010	OMB NO. 1004-013

SUNDRY	NOOD ATTIN	11 NMLC068430				
Do not use thi abandoned we	6. TF	Indian, Allottee or	Tribe Name			
SUBMIT IN TRI	7. If	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well ☐ Gas Well ☐ Oth	ner			ell Name and No. LU PIERCE CAN	IYON 33 FEDERAL 1	
2 Name of Operator CHESAPEAKE OPERATING,	INC. E-Mail: linda.goo	2111211000		PI Well No. 0-015-36636-0	0-X1	
3a Address OKLAHOMA CITY, OK 73154	1-0496	3b. Phone No. (include area code Ph: 405-935-4275		10. Field and Pool, or Exploratory WILDCAT		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Descript	ion)	11. (11. County or Parish, and State		
Sec 33 T24S R30E SESE 350 32.16799 N Lat, 103.87858 W			E	DDY COUNTY	, NM	
12. CHECK APPI	ROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPOR	T, OR OTHER	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Fracture Treat ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete		☐ Water Shut-Off ☐ Well Integrity ☐ Other	
Final Abandonment Notice Change Plans Plug and Abandon		Temporarily Abandon Drilling Operat				

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) determined that the site is ready for final inspection.)

☐ Plug Back

☐ Plug and Abandon

SPUD & SET SURFACE CASING:

5/8/2010 Spudded @ 1:00 pm.

5/9/2010 Run 13 3/8" 48# H-40 csg, set @ 714'. Cmt'd w/750 sx 1.75 yield, 13.5 ppg, circulated cmt back to surface. WOC.

Convert to Injection

5/10/2010 WOC 24 hours. Test 13 3/8" csg @ 1500 psi for 50 minutes - Good test. Compressive strength: 500 psi for 9 hrs 10 min.

(CHK PN 623048)

14 Thereby certify that the foregoing is true and correct Electronic Submission #86263 verified by the BLM Well Information System For CHESAPEAKE OPERATING, INC., sent to the Carlsbad Committed to AFMSS for processing by KURT SIMMONS on 05/11/2010 (10KMS1383SE)							
Name (Printed/Typea	U LINDA GOOD	Title	SR. REGULATORY COMPLIANCE SPEC				
Signature	(Electronic Submission)	Date	05/11/2010				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

Approved By ACCEPTED	JAMES A AMOS TitleSUPERVISOR EPS	Date	05/22/2	21
Conditions of approval if any are attached. Approval of this notice does not warrent or				

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.