	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
DistrictII	OIL CONSERVATION DIVISION	30-005-62884
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE X FEE
District IV	Salita Fe, Nivi 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		774 2404
	TEC AND DEPORTS ON WELLS	VA-2494
	CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
	ATION FOR PERMIT" (FORM C-101) FOR SUCH	Biplane SWD
PROPOSALS.)	,	8. Well Number
1. Type of Well:		3
Oil Well Gas Well	Other SWD	
2. Name of Operator	RECEIVED	9. OGRID Number
Yates Petroleum Corporation	ISE S F MANY	025575
3. Address of Operator	JAN 1 5 2004	10. Pool name or Wildcat
105 S. 4 th Street, Artesia, NM	88210 OCD-ARTESIA	11.72
4. Well Location		
Hair Lauren C. 22	10 for formal a North Process	1000 6 4 6 41
Unit Letter G: 23	10 feet from the North line and	1980 feet from the <u>East</u> line
Section 16	Township 6S Range 27E	NMPM Chaves County
Section 10	Township 6S Range 27E	NMPM Chaves County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
the first teach. How there was a property and the	4110'GR	
12 Check A	ppropriate Box to Indicate Nature of Notice	Report or Other Data
NOTICE OF INT		SSEQUENT REPORT OF:
TEN ON NEWEDIAL WORK	TEOGRAD ADAMOUNT	ALIENING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DR	ILLING OPNS. PLUG AND
		ABANDONMENT
_		
PULL OR ALTER CASING	MULTIPLE CASING TEST A	
PULL OR ALTER CASING	MULTIPLE CASING TEST A CEMENT JOB	
	COMPLETION CEMENT JOB	ND
OTHER:	COMPLETION CEMENT JOB OTHER: Began	ND
OTHER: 13. Describe proposed or complete	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, and the state of t	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complet of starting any proposed worth.	COMPLETION CEMENT JOB OTHER: Began	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, and the state of t	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work.	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, and the state of t	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing for the starting for the start	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, at k). SEE RULE 1103. For Multiple Completions: A crom surface to 410' to 1000 psi. Held good.	re-entry, production casing X ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing for 12/29/03 – TIH with 7-7/8" mill tooth	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, at k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'.	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pi	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, at k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate is 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL.	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, at k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate is 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL.	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion a 450 sx Super "H" with additives. 1/2" 15.5# AS-1 nickel coated packer with 2.25"
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pi 1/7/04 – TOC 4040' CBL. Perforate ston/off tool at 6280'. Acidize Silurian mins.	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. In bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1 with 6000g 20% HCL acid with 300 ball sealers. Proceedings of the sealers o	re-entry, production casing X and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion and 450 sx Super "H" with additives. 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pi 1/7/04 – TOC 4040' CBL. Perforate ston/off tool at 6280'. Acidize Silurian mins.	COMPLETION CEMENT JOB OTHER: Began eted operations. (Clearly state all pertinent details, ar k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1	re-entry, production casing X and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion and 450 sx Super "H" with additives. 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pi 1/7/04 – TOC 4040' CBL. Perforate son/off tool at 6280'. Acidize Silurian mins. I hereby certify that the information a	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. The bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1 with 6000g 20% HCL acid with 300 ball sealers. Proposed in the complete to the best of my knowledge bove is true and complete to the best of my knowledge.	re-entry, production casing X Indigive pertinent dates, including estimated date ttach wellbore diagram of proposed completion 1.450 sx Super "H" with additives. 1.72" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 The state of the
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pi 1/7/04 – TOC 4040' CBL. Perforate ston/off tool at 6280'. Acidize Silurian mins.	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. In bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1 with 6000g 20% HCL acid with 300 ball sealers. Proceedings of the sealers o	re-entry, production casing X and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion and 450 sx Super "H" with additives. 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 ge and belief.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian mins. I hereby certify that the information a SIGNATURE:	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A state of the completions of the completion o	re-entry, production casing Ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion A 450 sx Super "H" with additives. A 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 The supervisor DATE: January 12, 2004
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing for 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pin 1/7/04 – TOC 4040' CBL. Perforate son/off tool at 6280'. Acidize Silurian mins. I hereby certify that the information a SIGNATURE: Type or print name Tina Huerta	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A from surface to 410' to 1000 psi. Held good. The bit. Cleaned well out to 6523'. M. Set 5-1/2" 15.5# casing at 6523'. Cemented with Silurian 6326'-6386' for a total of 240 holes. Set 5-1 with 6000g 20% HCL acid with 300 ball sealers. Proposed in the complete to the best of my knowledge bove is true and complete to the best of my knowledge.	re-entry, production casing Ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion A 450 sx Super "H" with additives. A 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 The supervisor DATE: January 12, 2004
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing ff 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pt 1/7/04 – TOC 4040' CBL. Perforate on/off tool at 6280'. Acidize Silurian mins. I hereby certify that the information a SIGNATURE:	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A state of the completions of the completion o	re-entry, production casing Ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion A 450 sx Super "H" with additives. A 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 The supervisor DATE: January 12, 2004
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. 12/22/03 – Began re-entry procedures 12/23/03 – Tested 8-5/8" 24# casing for 12/29/03 – TIH with 7-7/8" mill tooth 1/3/04 – Reached TD 6523' at 9:00 Pin 1/7/04 – TOC 4040' CBL. Perforate son/off tool at 6280'. Acidize Silurian mins. I hereby certify that the information a SIGNATURE: Type or print name Tina Huerta	OTHER: Began eted operations. (Clearly state all pertinent details, and k). SEE RULE 1103. For Multiple Completions: A state of the completions of the completion o	re-entry, production casing Ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion A 450 sx Super "H" with additives. A 2" 15.5# AS-1 nickel coated packer with 2.25" essured annulus to 500# and held good for 30 The supervisor DATE: January 12, 2004

