

I received the approved Intent to P&A on the C.D.M. A Com #1, API No. 30-015-21687, 990 FNL 660 FWL Sec 29 T21S R27E, Eddy Cty, NM. I apologize, I must have forgot to attach a chronological of the work that was done prior to filing the Intent to P&A. We have been working on this well and have spent approximately \$333,000 trying to re-enter and fix this well. We have a fish in the hole consisting of a 4-3/4" bit, 6 - 3-1/2" drill collars, & 2-7/8" tbg with the TOF @ 3256' and BOF @ 11170'. While trying to get the equipment out of the hole, the casing collapsed @ 2680', at the last report they had gotten back to 1437'. The field feels that they can get back down to where the casing is collapsed, other than that we are out of ideas. Would you please review the plugging procedure and the work that we have already done and let us know what else we might do to P&A this well. We appreciate your help in this manner.

Thanks,  
David Stewart  
Sr. Regulatory Analyst  
OXY Permian  
432-685-5717  
Fax-432-685-5742