

OCD-ARTESIA

Form 3160-5
(February 2005)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.5. Lease Serial No.
LC-047633B

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other SWD

8. Well Name and No.

Ninty Nine SWD #1

38338

2. Name of Operator

Endurance Resources LLC

270329

9. API Well No.

30-015-27677

3a. Address

PO Box 1466 Artesia, NM 88211

3b. Phone No. (include area code)

575-308-0722

10. Field and Pool or Exploratory Area

SWD

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 990' FWL Sec 1 - T18S-R30E

11. Country or Parish, State

Eddy county

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other Re-Enter

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7/29/10 Start Re-entry

8/5/10 Dressed off 5 1/2" casing @ 800'

8/6/10 Run 820' 5 1/2" 17# csng cmt w/ 250 sxs class "C" 14.8# 1.32 yield circ 124 sxs to truck.

8/13/10 Cmt squeeze perfs 6843-7106 w/ 4005x5 class H 1% CaCl2

8/16/10 Start drill out

8/19/10 Spot 40 sxs plug across perfs 8370-8060 pressure to 2000#

8/20/10 Drill out

8/23/10 Ran pressure test 1800psi lost 180#

8/24/10 Spot 50 sxs class "C" @ 850' pressure to 2000#

8/26/10 Drill out

8/27/10 Spot plug 7156-6669' w/ 60 sxs class H pressured to 2000#

8/28/10 Drill out

8/30/10 Pressure test 1800# 30 min 1780#.

RECEIVED

SEP 29 2010

NMOCD ARTESIA

ACCEPTED FOR RECORD

SEP 26 2010

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Randall L. Harris

Title Geologist

Signature

Date

9/3/10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

DJJ

OK





