

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00054
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LINDENMUTH & ASSOCIATES, INC.		6. State Oil & Gas Lease No.
3. Address of Operator 510 HEARN STREET, SUITE 200, AUSTIN, TX 78703		7. Lease Name or Unit Agreement Name GORMAN STATE
4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>N</u> line and <u>1980</u> feet from the <u>W</u> line Section <u>36</u> Township <u>19S</u> Range <u>24E</u> NMPM County <u>EDDY</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 13343
		10. Pool name or Wildcat CANYON WOLFCAMP

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERNATE CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- * Mud laden must be placed between all Cement Plugs. Mixed at 25 sacks of gel per 100 bbls of water.*
1. Spot a 50 sx plug @ 5741'. WOC & tag plug.
 - * 2. Spot a 25 sx plug @ 4970'. Perforate & squeeze tag.*
 - * 3. Spot a 255 sx plug @ 3400' to cover B.S. Perforate & squeeze tag.*
 4. Perforate 5 1/2 csg @ 1050' & circulate cement up backside to surface. Shut-in valve @ surface and fill 4 1/2 csg to surface.
 5. Set PXA marker, clean & level location. Cut off anchors.

** Perforate & squeeze WOC Tag*

RECEIVED

OCT 29 2010

NMOCD ARTESIA

Spud Date: ASAP after NMOCC approval.

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE

Type or print name GERALD S. LINDENMUTH E-mail address: glindenmuth@llbcompany.com PHONE: 512-322-9779

For State Use Only

APPROVED BY: [Signature] TITLE DATE 11/1/2010


Conditions of Approval (if any):

Approval Granted providing work
is complete by 1/1/2011

LINDENMUTH AND ASSOCIATES, INC.
OIL AND GAS PRODUCERS

October 26, 2010

State of New Mexico
Energy, Minerals & Natural Resources
Oil Conservation Division
1301 W. Grand Ave.
Artesia, NM 88210



Re: Gorman State #1
Sec. 36-19S-24E
Eddy County, NM

Ladies & Gentlemen:

Enclosed is Form C-103 to PXA the Gorman State #1. Please let me know once this has been approved so I can get a rig and proceed with the PXA.

Sincerely,

A handwritten signature in black ink, appearing to be "G. Lindenmuth".

Gerald S. Lindenmuth
President

kt

Enclosure: Form C-103

M:\Vol2\KT\State Reports\New Mexico\C103\Gorman State #1--2010-1026 Letter.wpd