
Submit 1, Copy To Appropriate District Office	State of New Mexico				Form C-103	
District I	Energy, Minerals and Natural Resources			WELL API NO.	October 13, 2009	
1625 N. French Dr., Hobbs, NM 88240 District II	OH, GOMETHAL TROM DAVISION			30-015-01290		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of Lo	ease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE 🖂	FEE 🗌	
District IV 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Le	ease No.		
87505						
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM PROPOSALS.)			G BACK TO A	7. Lease Name or Unit Agreement Name EAST RED LAKE UNIT TRACT 1		
PROPOSALS.)		RECEIVED		8. Well Number 003		
Type of Well: Oil Well Gas Well Other Name of Operator		l NO	V 05 2010	9. OGRID Number		
TANDEM ENERGY CORPORATION			V U 3 ZUIU	10068		
3. Address of Operator 11490 WESTHEIMER RD, STE. 1000 HOUSTON, TX 7707			DD ARTESIA	10. Pool name or Wildcat RED LAKE;QUEEN-GRAYBURG, EAST		
4. Well Location						
Unit Letter_N_:_1980feet from theW line and660 feet from theSline						
Section 36 Township 16S Range 28E NMPM EDDY County						
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12. Check A	Appropriate Box to Ind	icate Na	ture of Notice,	Report or Other Dat	ta	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WO					TERING CASING	
			COMMENCE DRII	MMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	JOB 🗌		
DOWNHOLE COMMINGLE						
OTHER:		\neg	OTHER:		П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or recompletion. 1. SET CIBP @ 1617' – CIRCULATE PLUGGING MUD – SPOT 25 SACKS ON TOP						
2. PERF AND SPOT 25 SACKS @ 1150' – TAG						
3. PERF AND SPOT 25 SACKS @ 400' – TAG 4. PERF AND SPOT 25 SACKS FROM 60' TO SURFACE						
3. PERF AND SPOT 25 SACKS @ 400' - TAG 4. PERF AND SPOT 25 SACKS FROM 60' TO SURFACE 5. INSTALL PA MARKER - CLEAN LOCATION						
				1/2	د کی	
					10, 8 A	
					10/3	
					On Ori	
					(d) (D)	
·						
Snud Data	D: D	oloosa Dat		·		
Spud Date:	Kig Ke	elease Dat	e:		•	
I hereby certify that the information	above is true and complete	to the be	st of my knowledge	e and belief		
. 1	/ /		ov 0.1 y 0 10 u.g.	and some		
and the second s						
SIGNATURE AGENT DATE 11/4/10						
THEE AGENT DATE 11/4/10						
Type or print nameMARK HOSKINS E-mail address: PHONE: _575-736-1366						
For State Use Only						
APPROVED BY:	AL TITLE	onadA :	val Granted providi	ng work DATE	11/6/2000	
Conditions of Approval (if any): is complete by						
				,	•	

Well Name API #30-015-01290 EAST RED LAKE UNIT TRACT 1 # 3



25 SX @ 60' TO SURFACE'

25 SX @ 400' Surface Casing @ 350'

25 SACKS @ 1150'

CIBP @ 1617' WITH 25 SX ON TOP

Company Name:

TANDEM