Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and and the article and the article

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

FORM APPROVED

OMB	INO.	1004	-U ! J	S
Expires:	Nove	mber	30,	200

SUNDRY NOTICES AND REPORTS ON WELLS

NM-25365

ULLAND WANAGE WENT SBAD FIELD OFFICE Partment or agency of the United

5. Lease Serial No.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottec or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No		
1. Type of Well Oil Well Gas Well X Other SWD 2. Name of Operator					8. Well Name and No. Neff Federal #3 9. API Well No.		
OXY USA Inc. 16696							
3a. Address 3b. Phone No. (include area code)					30-015-28281		
P.O. Box 50250 Midland, TX 79710 432-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10: Field and Pool, or Exploratory Area Livingston Ridge Delaware			
430 FNL 760 FWL NWNW(D) Sec 25 T2				LIVINGSTON KI	uge Deraware		
430 THE 700 THE THIM (b) 300 23 TE	LO NOIL			11. County or Paris	sh, State		
12. CHECK APPROPRIATE	BOX(ES) TO INDICA	ATE NATURE OF I	NOTICE, REPO	ORT, OR OTHER	DATA		
TYPE OF SUBMISSION		TYI	PE OF ACTION				
Notice of Intent	X Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off		
Notice of filterin	Alter Casing	Fracture Treat	Reclamatio		Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomplete	:	Other Plug Brushy		
	Change Plans	Plug and Abandon	Temporaril		nyon, Recomplete		
Final Abandonment Notice	Convert to Injection	X Plug Back	Water Disp	<u> </u>	erry Canyon		
following completion of the involved operations. It testing has been completed. Final Abandonment I determined that the final site is ready for final inspection. 9/22/10 Converse Swo 1229.	Notices shall be filed only a ection.)	Ther all requirements, in PFR DATE OF PRINCE hed	cluding reclamation	n, have been comple			
14. I hereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>)	NMOCD RT	D Title					
David Stewart		Sr. Re	egulatory Ana	alyst			
Vn' Stat		Date VPV	किया हि	R RECORD			
THIS	S SPACE FOR FEDER	AL OR STATE OF	FICE USE				
Approved by		Title	NOV 2	2010 Date			
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the state of the conduct operations the state of th	those rights in the subject	nt or Office lease /s			BK		

Neff Federal #3

9/7/10 RU WL, RIH W/ PERF GUNS & PERF @ 6930', FLWD PKR FLD TO HALF TANK

9/8/10 PUMPED 45BBLS 10# BRINE DOWN TBG TO CIRC, NO SUCCESS, PUMPED 2BBLS DOWN CSG TO LOAD ANNULUS, PUMPED 150 BBLS DOWN CSG @ 2.5 BPM @ 450#, GOT PLASTIC & RUST FOR RETURNS, PUMPED 5 BBLS 14# MUD DOWN TBG AND 20 BBLS DOWN CSG TO KILL WELL, NDWH, NUBOP, REL PKR, POOH W/ INJECTION STRING, PROFILE NIPPLE & PACKER, RIH W/ 4 3/4 BIT, 6- 3 1/2 DC'S & 73 JTS WS, BIT @ 2478'

9/9/10 RIH W/WS & BIT, TAG CIBP @ 7530', RU SWIVEL & STRIPPER HEAD, PUMPED 100BBLS F/W DOWN CSG TO DILUTE MUD & 250 BBLS DOWN TBG TO CIRC MUD POOH, DRILLED ON CIBP FOR 3 HOURS & MADE 8", PULLED OFF PLUG & CIRC HOLE CLEAN, KILLED WELL W/8 BBLS 14# MUD, LD SWIVEL, PULLED 14 JTS, LEFT BIT @ 7020',

9/10/10 RIH W/ BIT TO 7531', RU SWIVEL, PUMPED 50BBLS F/W DOWN TBG TO DISPLACE MUD, REVERSED CIRCULATION & STARTED DRILLING ON CIBP, DRILLED THROUGH PLUG & FELL OUT @ 7532', RU & LD SWIVEL, POOH TO 7035', INSTALL FLOAT SUB, RIH & TAGGED @ 8410', CIRC HOLE CLEAN, PULLED BIT TO 7035', PUMPED 8 BBLS 14# MUD DOWN TBG.

9/11/10 PUMPED 20BBLS 14# MUD DOWN CSG & 8 BBLS DOWN TBG TO KILL WATER FLOW, POOH W/ WS, DC'S & BIT LAYING DOWN BIT & DC'S, RIH W/ WS & SN DOWN TO 8296', RU HES & SPOT 25SX CL H CMT FROM 8310-8170', PULL ABOVE CMT & REVERSED OUT, RD HES, POOH W/ WS. RU WL, RIH W/ CIBP & SET @ 8170', POOH W/ WL.

9/12/10 RIH W/ WS & SN DOWN TO 8156', RU HES & PUMP 25SX CI H CMT DOWN TBG, PULLED UP TBG & REVERSED OUT, RD HES, POOH W/ WS. RU WL, RIH W/ CIBP & SET @ 6990', RD WL, RIH W/ WS DOWN TO 6983', RU HES & PUMP 25SX CI H CMT DOWN TBG, RD HES, POOH W/ WS. RU WL & RIH W/ CIBP & SET @ 6229', POOH W/ WL.

9-13-10 TIH W/WS, RU HES, PUMP 30SX CMT, RD HES, WOC-4HRS. RIH & TAG CMT @ 6050', TOH W/WS.

9-14-10 RU WL, MADE 12 RUNS WITH PERF GUNS , PERF @ 5634-5987' W/ 4"TITAN EXP CASING GUN SYS, EXP 3325-321T SCP PROSPECTOR (EHD=4" PEN=45.16" @6 SPF) RD WL, TIH WITH PKR SET @ 5568 WITH 176 JTS

9-16-10 WAIT FOR THEM TO JET OUT ACID TANK, RU HES, ACIDIZED WELL w/ 10000 GAL NEFE ACID, SALT AS DIVERSION, SI PRESSURE 941#, AFTER 5 MIN 896#, 10 MIN 875#, 15 MIN 861#, RD HES

9-17-10 OPEN WELL TUB HAD 320#, CASING 480# BLEED DOWN WELL. REL PKR, TOH WITH TBG, LD PKR, TIH WITH 4-3/4" BIT, Rih & tag @ 6040', BOTTOM PERF @5987', TOH LD WS AND BIT


9-18-10 OPEN WELL 30# BLEED OFF, PU NEW 5-1/2" ARROW SET 1X PKR W/ 2-7/8" DUOLINE TBG, SET PKR @ 5543/ CIRC PKR FLD, NDBOP, NUWH, RAN PRE TEST CHART TO 500#, HELD GOOD SD.

9-20-10 RD UNIT CLEAN LOC

9-22-10 RUN MIT CHART FOR 30 MIN TO 530#, BLM WITNESS. WELL READY FOR INJECTION.

OK- PI-NMOSO

OXY USA Inc. - Current Neff Federal #3 API No. 30-015-28281



17-1/2" hole @ 810' 13-3/8" csg @ 810' w/ 1000sx-TOC-Surf-Circ

11" hole @ 4306' 8-5/8" csg @ 4306' w/ 1800sx-TOC-Surf-Circ

2-7/8" tbg w/ pkr @ 5568'

CIBP @ 6229' w/ 30sx Tagged 6050'

CIBP @ 6990' w/ 25sx

CIBP @ 8170' w/ 25sx 25sx @ 8310-8170'

PBTD-8418'

Perfs @ 7050-7068'

Perfs @ 5634-5987'

7-7/8" hole @ 8460' 5-1/2" csg @ 8460' DVT @ 3973' - 6177' 1st w/ 575sx-Circ Surf 2nd w/ 520sx-Circ Surf 3rd w/ 450sx-TOC-Surf-Circ

Perf @ 8220-8240'