Form 3160-5 (June 1990)

N.M. DIV-Dist. 2 1301 W. Grand Avenue **UNITED STATES**

Oil Cons.

DEPARTMENT OF THE INTERIOAITOSIA. NM 88210 **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No. **SUNDRY NOTICES AND REPORTS ON WELLS** NM 0556590 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Alottee or Tribe Name Use "APPLICATION FOR PERMIT -" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE RECEIVED OIL WELL GAS 8. Well Name and Number WELL. 1. Type of Well: OTHER FEDERAL 33 GAS COM MAR - 9 2004 2. Name of Operator OCD-ARTESIA 3 **CHEVRON USA INC** 3. Address and Telephone No. 9. API Well No. 15 SMITH ROAD, MIDLAND, TX 79705 915-687-737 30-015-32180 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 10. Field and Pool, Exploaratory Area Unit Letter Κ : 1980 Feet From The SOUTH Line and 2080 Feet From The LOAFER DRAW MORROW SE 11. County or Parish, State Township 21-S WEST Line EDDY . NM 12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans Recompletion **New Construction** Notice of Intent Plugging Back Non-Routine Fracturing Subsequent Report Casing Repair Water Shut-Off Atlering Casing Conversion to Injection Final Abandonment Notice OTHER: ADDITIONAL COMPL INFO Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this world ACCEPTED FOR RECORD 11-12-03: MIRU KEY #285. SET BLANKING PLUG @ 8579'. RU SWAB. 11-13-03: SWAB FL DN 1300-4200. TOH W/PKR. 11-14-03: SWABBING. 11-17-03: LATCH & REL PKR. TIH W/CIBP & SET @ 8715'. MAR - 8 2004 11-18-03: TIH W/PKR & SET @ 8635'. TIE IN FLOWLINE. RU SWAB. 11-19-03: SWAB. RIG DOWN, TIE WELL INTO SWAB TANK, RELEASE RIG. ALEXIS C. SWOBODA FINAL REPORT WELL TURNED OVER TO PRODUCTION

2-09-04: MIRU PU. REL PKR. TIH W/2 3/8" TBG. TAG @ 8693'. PUH TO 8460. (262 JTS IN HOLE)

2-10-04: TAG FILL @ 8693. PUH TO 8361. PUMP 350 BBLS 4% KCL. TIH W/BIT, TBG, & BAILER. TAG FILL @ 8693. BAIL SAND FR 8693-8715. TAG CIBP. DRILL ON CIBP @ 8715. D/O TO 8718. PUH TO 8518. 2-11-04: DO CIBP FR 8718. PUSH DOWN TO 8907. TIH W/2 3/8" TBG, PSI BOMBS LANDED @ 8672. 2-12-04: NO OPERATIONS. 2-13-04: NO OPERATIONS. 2-16-04: TIH W/CIBP & SET @ 8590'. TEST CIBP TO

2-17-04: DUMP 30' CMT ON TOP OF CIBP @ 8590'. PU RBP & WS. SET RBP @ 7375'. PUH TO 7296'. 2-18-04: PICKLE TBG W/500 GALS 15% HCL. SPOT 500 GALS 15% NEFE HCL FR 7296-6965. PUH TO 5954. 2-19-04: RU SWAB. 2-20-04: PERF 6994-98,7023-27,7093-7103,7118-28, 7151-61,

7199-7209 & 7271-81. PU R NIPPLE, TBG SUB, PKR, ON-OFF TOOL. TIH W/48 STANDS TO 3000'. 2-23-04: SET PKR. NU FRAC STACK. 2-24-04: ACID FRAC PERFS FR 6994-7281 W/40,000 GALS DGA329 20% HCL & 144 TONS CO2. RU SWAB.FLOW WELL TO TANK. 2-25-04: SWAB. 2-26-04: TIH W/2 3/8" PROD TBG. 2-27-04: RU SWAB. 2-28-04: SWAB. 3-01-04: FLOW BACK WELL. RIG DOWN, CLEAN LOCATION RELIGIO

	$=(\rho$		· · · · · · · · · · · · · · · · · · ·		
14. I hereby certify that the (freeling is true and correct SIGNATURE)	Teake TIT	LE_ Regulatory Specialist		DATE	3/2/2004
TYPE OR PRINT NAME	Denise Leake				
(This space for Federal or State office use)					
APPROVED CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE		
Title 18 U.S.C. Section 1001, makes it a crime for	any person knowingly and willfully	o make to any department or agency of the United State	es any false, fictitio	us or fraudulent stat	tements or

PETROLEUM ENGINEER