

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE DATE*
(Only if instructions on reverse side)

Form approved.
Budget Bureau No. 42 R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 030982

6. IF INDIAN, ALLOTTEE OR TRUST NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMITS" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Petroleum Corporation of Texas		8. FARM OR LEASE NAME Gorman Federal	
3. ADDRESS OF OPERATOR Box 911, Breckenridge, Texas 76024		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL and 2310' FEL, Section 26, T10S, R25E		10. FIELD AND POOL, OR WILDCAT Bitterlake, SA, South	
14. PERMIT NO. Unknown		15. ELEVATIONS (Show whether DE, RT, GR, etc.) Unknown	
		12. COUNTY OR PARISH Chaves	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Change of operator from Earl J. Cotton

Propose to plug and abandon Well No. 2. Plugging procedure is as follows:

- (1) Dump 15 sacks cement @ 1332'
- (2) Fill hole w/10# mud
- (3) Place 2 sacks cement @ surface
- (4) Set steel marker
- (5) Level location and fill pits (if any)

You will be notified in advance as to the time and date that each plug will be set so that you may have a representative present to witness same.

RECEIVED

JUN 23 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

U. S. G.
ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

Mary B. Taylor

TITLE

Production Clerk

DATE

June 17, 1970

(This space for Federal or State comments)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 23 1970

R. L. BECKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side