

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Charles W. Harle	3. Address of Operator P.O. Box 354 Roswell, N.M. 88201	4. Location of Well UNIT LETTER <u>I</u> 1980' FEET FROM THE <u>South</u> LINE AND <u>660</u> ' FEET FROM THE <u>East</u> LINE, SECTION <u>9</u> TOWNSHIP <u>11South</u> RANGE <u>25 East</u> N.M.P.M.	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	5. State Oil & Gas Lease No.
APR 4 1980 O. C. D. ARTESIA OFFICE				7. Unit Agreement Name	
				8. Farm or Lease Name Barbe	
				9. Well No. #1	
				10. Field and Pool, or Wildcat Hondo San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 3460 GR				12. County Chavez	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug & abandon the Barbe #1
We propose to pump 10 barrels of fresh water ahead of cement to clear casing & to make sure formation will take fluid.
Then we propose to pump 85 sacks of class C neat cement in to perforations and leave 4½" casing full of cement to the surface.
No tubing in hole.
Location and pits will then be cleaned up & dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Chuck Cov

TITLE AGENT

DATE 4-1-80

APPROVED BY

W.A. Gussert

TITLE

SUPERVISOR, DISTRICT II

DATE

APR 4 1980

CONDITIONS OF APPROVAL, IF ANY: