

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
NEW MEXICO SCHOOL OF MINES
SOCORRO, NEW MEXICO

NOTICE OF INTENTION TO SHOOT WELL

Notice must be given to the State Geologist or to the proper Oil and Gas Inspector at least five days before beginning work, and work should not begin until approval is obtained. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to sender. Submit this notice in duplicate.

..... Roswell N. Mex., May 12 19 32

Mr.

State Geologist,
Socorro, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to shoot Warman Oil Syndicate Well
No. 1 in NE 1/4 of Sec. 15 T. 14 S., R. 25 E., N. M. P. M.,
..... Oil Field Chaves County

Unless already filed a copy of the well log accompanies this notice. Present production is
..... barrels per day of oil and No. barrels per day of water. Water comes in at No. water
Formation to be shot: Top is at 1142 feet, bottom at 1162 feet.

Inner string of casing set at 980 feet.

Well is to be shot with 40 quarts.

Purpose of shot is Crack up hard formation

Name of torpedo company or shooter is New Mexico Glycerine Co.

Additional information: Formation is black sandy lime giving up about one
barrell of free oil per day, asphalt base 20 gravity. Hole is free from
any water. 5-3/16" 20 lb pipe was set in 30 feet of shale mud on bottom
of very hard lime completely shutting off the water. 8" heavy pipe was
set in top of lime at 620'. Antecision water at 720'. Black sulphur water
at 912'. Total depth 1230 saturated black lime.

DUPLICATE

Approved 5-13 1932 Sincerely yours,

Except as follows:

*After talking to Dr. Wells
regarding this well.*

.....
Company or Operator

By C. J. Warman (Signed)

Position Manager

Send communications regarding well to

Name C. J. Warman

Address Box 72, Roswell, N. M.

L. J. Shumaker
State ~~Geologist~~ or Oil and Gas Inspector.