

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

E-4937

SUNDY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator H. F. JONES		8. Farm or Lease Name Levers State
3. Address of Operator P. O. Box 1057, Roswell, N. M. 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1650</u> FEET FROM THE <u>N</u> SIDE AND <u>1650</u> FEET FROM THE <u>E</u> LINE, SECTION <u>32</u> TOWNSHIP <u>36</u> RANGE <u>6E</u> NMPM.		10. Field and Pool, or Wildcat Pecos San Andres
15. Elevation (Show whether BP, RT, GR, etc.)		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL UP ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Aug 1, 9 and 10th 1991

to location and rigged up. ...  
set 15 sacks of cement at T. D. 1150  
in mud, pull tubing up to 400', ... plug at 400' and purged in mud.  
pull out tubing and set 5 sacks of cement ...  
regulation steel washer.  
mud pits and clean location.

Plugged in Compliance with Order M-7878.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED George A. Williams TITLE Managing Co Contractor DATE 8-22-91

APPROVED BY W. A. Gressett TITLE Commissioner DATE 8-22-91

CONDITIONS OF APPROVAL, IF ANY: