

C/35

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
TO THE DISTRICT OFFICE ON
RECEIVED BY
DEC 27 1984
O. C. D.
ARTESIA, OFFICE

EXPIRES
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 067811
2. NAME OF OPERATOR Stevens Operating Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
3. ADDRESS OF OPERATOR P. O. Box 2203 Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650 FNL, 330 FWL, Sec. 33, T-7-S, R-26-E		8. FARM OR LEASE NAME Nichols Dale Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether or, ft, or, etc.) 3683 GR		10. FIELD AND POOL, OR WILDCAT Pecos San Andres
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-7-S, R-26-E
		12. COUNTY OR PARISH Chaves
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

☐
☐
☐
☐
☐

PLUG OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

☐
☐
☒
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

☐
☐
☐
☐

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

☐
☐
☐
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

8 5/8 surface csg @ 103' cement circ. 4 1/2 Production csg @ 1170' cement circ. PBTD 1166'. San Andres Perforations: 1128'-1160'.

P & A Proposal:

1. Set cement plug 1050' to 1165' to cover perms 1128'-1160'. Tag plug.
2. Set cement plug surface to 50'.
3. Set dry hole marker.

Per verbal approval 12-12-84 by Pete Chester.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Controller

DATE 12-13-84

(This space for Federal or State Approval)

APPROVED (Orig. Sgd.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEC 23 1984

*See Instructions on Reverse Side