Approval expires 12-31-60.	
05827	
Unit	

NOTICE OF INTENTION TO DRILL	S	IRSFOLIENT REPORT (F WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS.			F SHOOTING OR ACIDIZING	1 1
NOTICE OF INTENTION TO TEST WATER SHU	1 1		F ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR RE			F RE-DRILLING OR REPAIR	i
NOTICE OF INTENTION TO SHOOT OR ACIDI	! !!	JBSEQUENT REPORT	F ABANDONMENT	······································
NOTICE OF INTENTION TO PULL OR ALTER	ASING SUPPLEMENTARY		HISTORY	<u>-</u>
NOTICE OF INTENTION TO ABANDON WELL.				
(INDICATE ABO	OVE BY CHECK MARK NATUR	OF REPORT, NOTICE,		43
	•		February 17	19 53
Well No. 1 Sec. 26 T.			ft. from $\left\{egin{array}{c} \mathbf{E} \\ \mathbf{W} \end{array}\right\}$ line of	sec. 26
(1/4 Sec. and Sec. No.)	(Twp.) (Range)	(M	eridian) New Mexico	
Wildcet (Field)	(County or Subdi	vision)	(State or Territory)	
	ing points, and all other in	portant proposed wo	,	
OWWO				
OWWO 78 to 1510' . 5½° ⊚ 1	470' w/100 sx. C	р н @ 1470-1 5	10'. Acidized w/3	000 gals.
PB to 1510'. 5½" ⊕ 1				BOPD. I
78 to 1510'. 5½" ⊕ 1. frectured w/40,000 go			nd. Well rested 1/2	INED
PB to 1510'. 5½" ⊕ 10 frectured w/40,000 go	als. XW and 19,70	00 lbs . 20-40 :	id. Well tested 1/2 REEE	1 80PD. 1 1 1 1 E D 1 1 1 1 1 3
PB to 1510'. 5½" © 1. frectured w/40,000 get to P & A. I understand that this plan of work must	at receive approval in writing	00 lbs . 20-40 :	id. Well tested 1/2 REEE	1 80PD. 1 1 1 1 E D 1 1 1 1 1 3
PB to 1510'. 5½" ⊕ 10 frectured w/40,000 go	als. XW and 19,70 at receive approval in writin	00 lbs . 20-40 :	id. Well tested 1/2 REEE	1 80PD. 1 1 1 1 E D 1 1 1 1 1 3