


Land Office New Mexico
Lease No. 08139
Unit M

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Roswell, N. Mex. - September 8, 1958

Leonard-Federal White
Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 9
SW 1/4 Sec. 9 4S 27E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3897 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilling Mud TD (6713') to 6500 - 20 sx cement plug 6500-6435
" " 6435-5215 - 20 sx cement plug 5215-5150
" " 5150-2815 - 20 sx cement plug 2815-2750
" " 2750-50 - 15 sx cement plug 50 to surface.

Have erected regulation marker and location and pits have been returned to their original condition.

NOTE: 1475' of 8-5/8" casing was left in hole.

Location was cleaned up and marker erected.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company LEONARD OIL COMPANY
Address Box 708
Roswell, New Mexico
By [Signature]
Title Secretary-Treasurer.