

**U.S. CONSERVATION COMMISSION**

P. O. BOX 871

SANTA FE, NEW MEXICO

**RECEIVED**

**JAN 6 1961**

**O. C. C.  
ARTESIA, OFFICE**

**RECEIVED**

**JAN 6 1961**

**O. C. C.  
ARTESIA, OFFICE**

**January 5, 1961**

**Honolulu Oil Corporation  
P. O. Drawer 1391  
Midland, Texas**

**Attention: Mr. George R. Hoy**

**Gentlemen:**

**Reference is made to your letter of December 30, 1960, wherein you request authority to produce your State "B" Well No. 1, Chisum Pool, Chaves County, New Mexico, by means of a casing type rod pump without tubing.**

**Inasmuch as it appears that this well was completed with an exceptionally good casing and cementing program, there seems to be relatively little danger of waste being caused by the proposed method of production. Honolulu Oil Corporation is, therefore, hereby authorized to produce the subject well in the manner outlined in your letter of December 30, subject to the normal daily and monthly tolerances outlined in Rule 502.**

**It is suggested that you continue to observe this well for the possible effects of corrosion, since it is known that a corrosive problem does exist here, to some extent.**

**Very truly yours,**

**A. L. PORTER, Jr.  
Secretary-Director**

**ALP/DSN/ir**

**cc: Mr. M. L. Armstrong - Artesia, New Mexico**

RECEIVED

JAN 6 1961

U.S. DEPT. OF THE INTERIOR  
WASHINGTON, D.C.

RECEIVED

JAN 6 1961

U.S. DEPT. OF THE INTERIOR  
WASHINGTON, D.C.

Division of Conservation  
U.S. DEPT. OF THE INTERIOR  
WASHINGTON, D.C.

Re: George W. Brown

Dear Sir:

Reference is made to your letter of December 21, 1960, wherein you request authority to produce your share of well No. 1 in the field, Chavez County, New Mexico, in name of a casing type and casing without casing.

Inasmuch as it appears that this well was completed with an exceptionally good casing and cementing program, there seems to be relatively little danger of water being caused by the proposed method of production. Therefore, Division of Conservation, Bureau of Land Management, is authorized to produce the subject well in the manner outlined in your letter of December 20, subject to the normal safety and monthly tolerances outlined in Rule 201.

It is suggested that you continue to observe this well for the possible effects of corrosion, since it is known that a corrosive problem does exist here, to some extent.

Sincerely yours,

W. A. RUTHERFORD, Jr.  
Secretary-Director

W. A. RUTHERFORD, Jr.

cc: Mr. W. A. Rutherford, Jr., Secretary-Director, Bureau of Land Management, Washington, D.C.