

| | |
|------------------------|----|
| NO. OF COPIES RECEIVED | 6 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1- |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 4 |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. |
| E-9798 |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Ernest A. Hanson | 8. Form or Lease Name State "CS" |
| 3. Address of Operator P. O. Box 1515, Roswell, New Mexico | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>12-S</u> RANGE <u>27-E</u> NMPM. | 10. Field and Pool, or Wildcat Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3808' | 12. County Chaves |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|--|---|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/28/66 Rig-up cable tools.

1/29/66 Commence re-entry and clean out old hole to 2410'.

1/30/66 Run logs.

1/31/66 thru 2/7/66 Shut down for orders.

2/ 8/66 Set 20 sack cement plug @ 2355-2410'.

2/ 9/66 Ran 5-1/2", 15-1/2#, J-55 casing @ 2354' & cemented with 150 sx. neat Incor. WOC 24 hrs.

RECEIVED

FEB 21 1966

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harry T. Johnson TITLE Geologist DATE 2/10/66

APPROVED BY W. A. Gressett TITLE W. A. Gressett DATE FEB 21 1966

CONDITIONS OF APPROVAL, IF ANY: