

COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	2
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
OCT 4 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTEBIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name O'Brien "C"	
9. Well No. 2	
10. Field and Pool, or Wildcat Twin Lakes Devonian	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Stevens Oil Company
3. Address of Operator P.O. Box 1797, Santa Fe, New Mexico	4. Location of Well
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 9S RANGE 28E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3936 GL	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER **Progress of Workover** ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/24/76 Went in hole & fished tubing from hole.
6/2/76 Drilled out bridge plug @ 2600', drilled to 2800' on cement plug. Sqzd old perfs 2610-30, 2634-42 w/100 sx RFC Cement. WOC 36 hrs.
6/9/76 Drilled out plugs @ 2610-42, 2917, and 7261. T.D. 7295.
7/1/76 Perf 2564-92, 7249-55, 7264-72, acidize 7264-72 w/250 gals 7 1/2% acid, swb wtr w/s/o. Set Retr. B.P. @ 7260, H/w 1000 gals BDA, Commun. w/lower perfs. Swb wtr w/s/o.
Retrieve B/P @ 7260, reset @ 2722. Acidize perfs 2564-92, w/6000 gals 20%. Swab acid, oil and water.

POSTED
ID-1
10-8-76
res-entry

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *David G. Stevens*

TITLE Owner

DATE 7/16/76

APPROVED BY *W. A. Gressett*

TITLE SUPERVISOR, DISTRICT II

DATE OCT 6 1976

CONDITIONS OF APPROVAL, IF ANY: