STATE OF NEW MEXICO INERGY AND MINERALS DEPARTMENT

MG. OF COPIES SCCEIVES	T	
DISTRIBUTION		1
SANTA FE	T_{i}	
FILE		1
U.S.O.S.		
LAND OFFICE		
OPERATOR	7-	

OIL CONSERVATION RECEIVED

Form C-103 -

		1. O. BOX .	· ·		Revised 10-1-78
SANTA FE		SANTA FE, NEW M	IEXICO 87501	•	
FILE		•	AUG 1 3 1982	Sa. Indicate Typ	o of Lease
U.S.O.S.			1100 I 0 130Z	State	Foo X
LAND OFFICE			0.00	5. State Oil & C	
OFERATOR			O. C. D.	3, state 311 g c	103 E (030 110;
			ARTESIA OFFICE		
	SUNDRY NOTICE	S AND REPORTS ON WI	EL LS		
(DO NOT USE THIS FO	ORM FOR PROPOSALS TO DR : **APPLICATION FOR PERMI	ILL OR TO DEEPEN OR PLUG BACK IT -** (FORM C-101) FOR SUCH P	TO A DIFFERENT RESERVOIR. (ROPOSALS.)		
				7. Unit Agreeme	ent Name
01L X 6A8	.L OTHER-				
Name of Operator				8, Farm or Leas	se Name
·				<u> </u>	_
Stevens Or	perating Corpora	ation		Rancho E	<u> Larico</u>
Address of Operator				9. Well No.	
P. O. Box	2408, Roswell,	New Mexico 88201		1 #1	and Chesen
Location of Well				10, Field and P	
т.	1980	ET FROM THE South	LINE AND 660 F		ges-San Andres
UNIT LETTER L		ET FROM THE	LINE AND F	EET PROM	$mmi\tilde{r}$
	10	•••	00-		
THE West	LINE, SECTION	TOWNSHIP	RANGE 28E	имрм.	
					77/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/
	///////////////////////////////////////	5. Elevation (Show whether DF	, RT, GR, etc.)	12. County	/////////
		3749 GR		Chaves	
e,	Charle Anneancia	<u> </u>	D.		
		e Box To Indicate Nat			
NOTI	CE OF INTENTION	то:	SUBSE	EQUENT REPORT OF	·:
_	<u></u>	_1			
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	ALTE	ERING CASING
HOOKANILY ABANOON	7		COMMENCE DRILLING OPNS.	K PLUS	AND ABANDONMENT
FULL OR ALTER CASING			SASING TEST AND CEMENT JOB	7	
The on Action capital	- -1			ions and treatmer	nt X
			OTHER	ions and creatner	<u>ıc [A</u>
OTHER					
Describe Described on C	ampleted Operations (Cla	early state all pertinent details		i-luding antiqued data a	f
work) SEE RULE 1103.	ompleted Operations (Cie	early state all pertinent details	t, and give pertinent dates,	including estimated date o	i starting any proposed
• ••					
7-20 - 82	Washed over 20	O' of dry hole mark	ker, started in ho	ole.	
		1	·		
7-22-82	Cleaned out ho	ole to 21/8!			
7-22-62	Cleaned out in	oie w 2146 .			
7 04 00	D (C) (1 1 -1	2045 5 46 46 5		76 76 5 70 5	
7-24-82		2045.5, 46, 46.5,		/6, /6.5, /9.5,	
	80, 80.5, 84,	84.5, 87, 87.5, 88	3, 88.5.		
	•				
7-25-82	Ran 63 its 2 3	3/8" tubing, set pa	acker at 1973.5.	Acidize w/7000	gals
	28% HCL.	3, = 1			•
	200 Hell.				
7 27 22	D	2102 5 04 04 5	07 07 5 12 5	14 . 14 E	
7-27-82	reriorated at	2103.5, 04, 04.5,	UI, UI.5, 13.5, .	14, 14.5.	
7-29-82	Acidized w/450	000 gals 28% HCL, (500# salt, 300# B	.F.	
7-31-82	Set tubing at	2124'. Set pump	iack.		
			, - : 		

	ONS OF APPROVA	LI IE AND.				
^ P # O ∀ € B	· Silus	Il Coment	YITLE	SUPERVISOR, DISTRICT II	DAYC _	AUG 1 9 1982
	Sit 14.)://1-	TITLE	Production Coordinator	DATE	8-12-82
	· · · · · · · · · · · · · · · · · · ·	information above is true and co	omplete to the be	est of my knowledge and belief.		
	7–31–82	Set tubing at 2124	e • Sec p	mip jack.		