

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions reverse side)

Budget Bureau No. 1004-0155
Expires August 31, 1985

RECEIVED BY

MAR 19 1985

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER
2. ARTESIAN OFFICE ☒ ☐ ☐

HANSON OPERATING COMPANY, INC. (FOSSIL FUEL, INC.)

3. ADDRESS OF OPERATOR

P. O. BOX #1515, ROSWELL, NEW MEXICO 88202-1515

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

595' FNL & 718' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3592.7' DF

5. LEASE DESIGNATION AND SERIAL NO.

NM 8363

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

HANSON FEDERAL 22

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes. Sams Ranch

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 22, T. 14S, R. 28E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Test & evaluate

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to test the existing perfs (1578-88', 1596-1614', 1658-62', 1688-96', 1720-34', 1750-58', 1774-76' & 1784-92') by setting a packer above the perfs, acidize the zone, swab test and evaluate.
If commercial production is not indicated, we plan to plug & abandon the well.

18. I hereby certify that the foregoing is true and correct

SIGNED

Brenda H. Witt

TITLE Production Analyst

DATE 03/04/85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

MAR 13 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side