

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Triassic	0	328	Lime & Sand	Queen	1628	1628
Permian	328	1628	Salt with Lime streaks	San Andres	2186	2186
Queen, Grayburg	1628	2186	Sand, Lime & Anhydrite	Tubb	5019	5019
San Andres & Glorieta	2186	5019	Dolomite, Anhydrite, & Sand	Abo	5820	5820
Tubb	5019	5820	Dolomite, Anhydrite, & Sand	Wolfcamp	6412	6412
Abo	5820	6412	Dolomite, Anhydrite, & Sand	Upper Chester	9060	9048
Wolfcamp, Pennsylvania	6412	9060	Lime & Shale	Miss. Lime	9264	9218
Upper Chester	9060	9264	Shale & Lime	Woodford	9654	9585
Mississippian	9264	9654	Lime & Chert	Devonian	9715	9627
Miss. Woodford	9654	9715	Shale			
Devonian	9715	9748 T.D.	Dolomite			

38. GEOLOGIC MARKERS