

RECEIVED BY

BUREAU OF LAND MANAGEMENT

Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

LEASE DESIGNATION AND SERIAL NO.

Fed. Lc-068127

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Federal

8. FARM OR LEASE NAME

Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Linda San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 33, T6s, R26E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

2. NAME OF OPERATOR

H. L. Prince

3. ADDRESS OF OPERATOR

P. O. Box 129, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

330' F. L. L. & 2310 F. W. L.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3614 G R

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRAC TREAT

MULTIPLE COMPLETE

FRAC TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. OTHER, UNRECORDED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pertinent work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plug and abandon as follows:

Pump 15 sacks of cement with fresh water mixture on bottom of well inside of oil string casing. *Tag plug (top of plug at least 970')*

Pump mud from top of 15 sack cement plug to within 150 feet of surface.

Pump cement with fresh water mixture from 150 feet to surface.
Need 100' cmt. in 4 1/2" annular, 150'-50'.

Set 4" X 6' pipe for well marker with full legal description of well in welded lettering on pipe and weld marker to casing.

Remove all debris from well site.

18. I hereby certify that the foregoing is true and correct

SIGNED *H. L. Prince*

TITLE *operator*

DATE *3/6/85*

(This space for Federal or State office use)

APPROVED BY

APPROVED
PETER W. CHESTER

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 7 1985

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA