

RECEIVED

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

O. C. C.  
ARTESIA, OFFICE

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Sam G. Dunn Oil Operations		8. Farm or Lease Name Beadle
3. Address of Operator P. O. Box 3095 - Lubbock, Texas 79410		9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> , <u>2326.5</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>7S</u> RANGE <u>26E</u> NMPM.		10. Field and Pool, or Wildcat Linda San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3599.7		12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Temporary <del>plug and</del> abandon</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-16-69

Pull rods and tubing, remove surface equipments.  
Casing left in the hole with cap screwed on the top of casing for protection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. T. Thomas TITLE Geologist DATE 7-28-69

APPROVED BY W. A. Gressett TITLE SENIOR GAS INSPECTOR DATE AUG 1 1969

CONDITIONS OF APPROVAL, IF ANY: