

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIAL  
(Other instructions  
reverse side)DATE  
reForm approved  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LOC 68123

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

~~Grandall-Phillips~~

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Linda San Andres

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

S34, T68, R26E

12. COUNTY OR PARISH

Chaves

13. STATE

N.MEX.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR

H. E. Prince

3. ADDRESS OF OPERATOR

606 N. Atkinson, Roswell, New Mexico, 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

Unit Letter L, 1650' from S. Line  
331.73' from W. line.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3680.3' G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

Plug and abandon well as follows:

Well Depth 1210 ft.

Run 15 sacks of cement from 1210' back to 1029.10', Cut casing at 811.50'  
from surface.

Run Mud from 1029.10 back to 155'

Run 100' cement plug 50' in and 50' out of surface pipe.

Run mud from 55' back to 10'.

Run cement from 10' to surface and set marker.

Clean debris from site.

RECEIVED  
OCT 17 1975  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H. E. Prince

TITLE

Owner

DATE

10-10-75

(This space for Federal or State office use)

APPROVED BY  
DEC 6 1975APPROVED SUBJECT TO POSSIBLE ADDITIONAL  
REQUIREMENT THAT PAD AND/OR ROAD  
BE RIPPED AND SEEDED

DATE

\*See Instructions on Reverse Side

CONTACT THE U.S. GEOLOGICAL SURVEY  
BEFORE PROCEEDING