

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. O. C. C. COPY
SUBMIT IN TRIPlicate
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. NAME OF OPERATOR <u>H. E. Prince</u></p> <p>3. ADDRESS OF OPERATOR <u>606 N. Atkinson, Roswell, New Mexico, 86201</u></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>Unit letter O-900' from S. line</u> <u>2310' from E. line</u></p> <p>14. PERMIT NO. _____</p>	<p>5. LEASE DESIGNATION AND SERIAL NO. <u>LC-068127</u></p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME _____</p> <p>7. UNIT AGREEMENT NAME _____</p> <p>8. FARM OR LEASE NAME <u>Federal</u></p> <p>9. WELL NO. <u>2 Elliot Federal</u> <u>7</u></p> <p>10. FIELD AND POOL, OR WILDCAT <u>Linda San Andres</u></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>S 33, T 6 S, R 26 E</u></p> <p>12. COUNTY OR PARISH _____</p> <p>13. STATE <u>N. M.</u></p>
<p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3615 G. R.</u></p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plug and abandon as follows:

Well depth 1119 ft.

Run 15 sacks of cement from 1119 ft. back to 937.10 ft.

Cut casing at 720 ft. from top of surface.

Run mud from 937.10 back to 150 ft.

Run 100 ft. cement plug 50 ft. in and 50 ft. out of surface pipe.

Run Mud from 50 ft. back to 10 ft.

Run cement to surface and set marker.

Clean debris from site.

RECEIVED
MAR 25 1975
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED H. E. Prince TITLE Owner DATE 3-20-75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
MAR 25 1975
K. L. BEEKMAN
ACTING DISTRICT ENGINEER