

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

M. E. W. Enterprise

3a. Address

300 South Kentucky - Roswell, NM 88201

3b. Phone No. (including area code)

(505)627-2065

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter K - Sec 33-06S-26E

5. Lease Designation and Serial No.

NMLC068127

6. Allottee of Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

Federal

8. Well Name and No.

004

9. API Well No.

30-005-10062

10. Field and Pool, or Exploratory Area

Linda San Andres

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug & Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on the file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CASINGS  
8 5/8 101'  
4 1/2 1075'  
perfs 1000'-25'

MIRU well, pull production Eqp. Dump sand across perfs to 950', dump bail 30' cmt, displace hole w/ Gelled Brine, perf @ 100' pump 100' cmt plug pull out of hole & pump 20' surface plug. Install

dry hole marker - clean location.

Set 100' plug on top of sand & tag

Set 100' plug at 950' - 850'

Perf @ 150' + 8 5/8 to surf. Set 100' plug from 150' - surf.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Russell Whited

Signature

Title

Owner - Operator

Date

01-26-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

G. G. ten

Title

P.E.

Date

1/29/02

Cons  
appli  
appli

Accepted for record

not warrant or certify that the  
which would entitle the

Office

RFO

only

FEB 5 2002

RECEIVED  
2002 JAN 28 AM 10:27  
ELECTRONIC JUDICIAL  
ADMINISTRATIVE OFFICE