

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

Oil CONSERVATION DIVISION
RECEIVED BOX 2088
SANTA FE, NEW MEXICO 87501
MAY 12 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Brady W. Production, Inc.	8. Farm or Lease Name Pendergrass
3. Address of Operator P.O. Box 9128, Midland, Texas 79708	9. Well No. 1
4. Location of Well UNIT LETTER D 330 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 7S RANGE 26E NMPM.	10. Field and Pool, or Subcat Linda San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 3602.75 RL	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

March 18, 1987-Ran 1" pipe between 4 1/2" Production and 8 5/8" Surface Casing, Set @ .147' Mixed and pumped 20 sx. Portland Cement. Pull 1"

March 19, 1987-Ran 1"-Tagged Cement @ 105'-Mixed and pumped 10 sx. Portland Cement-Pull 1"

March 20, 1987-Ran 1"-Tagged Cement @ 60'-pull 1"-Ran 2 3/8" tubing @ 1020'-Mixed and pumped 25sx. Portland Cement-Pull 2 3/8 Tubing.

March 21, 1987-Ran 2 3/8" tubing-Tagged Cement @ 810'-Mixed and pumped 17 bbls-10# bentonite Mud-Pull Tubing to 146'-Mixed and pumped 10 sx. Portland Cement-Pulled tubing-Set Marker- All Casing left in well. Location cleaned-pits leveled.

Post IO-2
5-15-87
Pg A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. H. Brady</u>	TITLE <u>President</u>	DATE <u>May 11, 1987</u>
APPROVED BY <u>Danell Moore</u>	TITLE <u>Geologist</u>	DATE <u>12/3/87</u>
CONDITIONS OF APPROVAL, IF ANY:		