

NO. OF COPIES RECEIVED	<input checked="" type="checkbox"/>
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION  
**OCT 15 1974**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**O. C. C.**  
ARTESIA, OFFICE

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name
STURGEON
9. Well No.
1
10. Field and Pool, or Wildcat
LINDA SAN ANDRES
12. County
Chaves

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
H. E. PRINCE
3. Address of Operator
606 N. ATKINSON, ROSWELL, NEW MEXICO, 88201
4. Location of Well
UNIT LETTER <b>F</b> <b>1650</b> FEET FROM THE <b>W</b> LINE AND <b>1650</b> FEET FROM THE <b>N</b> LINE, SECTION <b>33</b> TOWNSHIP <b>6S</b> RANGE <b>26E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3605 G R

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**PLUG AND ABANDON AS FOLLOWS:**  
WELL DEPTH 1053 ft.  
RUN 15 SACKS OF CEMENT FROM 1053 back to 872.10'  
CUT CASING AT 654.50' FROM SURFACE  
RUN MUD FROM 872.10 BACK TO 155'  
RUN 100' CEMENT PLUG FROM 155' BACK TO 55', 50' IN AND 50' OUT OF SURFACE PIPE.  
RUN MUD FROM 55' BACK TO 10'  
RUN CEMENT FROM 10' BACK TO SURFACE AND SET MARKER  
CLEAN DEBRIS FROM SITE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. E. Prince TITLE OWNER DATE 10-10-74

APPROVED BY W. A. Gruesz TITLE OIL AND GAS INSPECTOR DATE OCT 23 1974

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging