BELEIVER

						13		· 14	"E.L. Too		
NO. OF COPIES RECEIVED	4								Form C-103		
DISTRIBUTION						ERVATION COMM	3111 2	5 h 10	6 Supersedes O	ld 103	
SANTA FE	1		NE	W MEXICO OI	L CONS	ERVATION COMM	IISSION -	_ 4 10	Effective 1-1-	65	
FILE	1	_					و رستي	- -			
U.S.G.S.							ا .نا ARTESI	L. LA	Tr. Indicate Type	of Lease	
LAND OFFICE							ARTESI	A, UF	State	Fee	, 🔀
OPERATOR	-	+						—	5, State Oil & Go	s Lease No.	
0, 2,,,,, 0,,		<u></u>									
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (POR G-101) FOR SUCH PROPOSALS;)											
1. OIL X GAS	,]	ER-						7. Unit Ägreemen	t Name	
2. Name of Operator		, OTA		 					8. Farm or Lease	Name	
Sam G. Dunn Oil Operations									Sturgeon		
3. Address of Operator		-I opera							9. Well No.		
· ·	2005	5 T., hh.	0015	Towas					2		
P. O. Box 3095 - Lubbock, Texas									10. Field and Pool, or Wildcat		
4. Location of Well									10, Field did Po	or writed	
UNIT LETTERF		2329	FEE	T FROM THE	<i>l</i> est	LINE AND	10 FEET	FROM	Linda Sa	n Andres	
THENorth	LINE	RECTION	33	TOWNSHIP	6 S	RANGE	26E	NMPM.			11111
182	LINE, S	SECTION		TOWNSHIP		75092				////////	
	TT	THIII.	15.	Elevation (Show	whether	DF, RT, GR, etc.)			12. County	111111	7777
	////	///////	\mathcal{N}						Chaves		/////
	7777.	<i></i>	<u> </u>								7777
10,	Che	eck Approj	priate	Box To Indi	icate N	lature of Notice	e, Report o	r Othe	er Data		
NOT	ICE C	OF INTENT	T NOI	го:	!		SUBSEQ	UENT	REPORT OF:		
PERFORM REMEDIAL WORK	\neg			PLUG AND ABANI	DON []	REMEDIAL WORK		7	ALTER	ING CASING	
TEMPORARILY ABANDON	╡				_	COMMENCE DRILLIN	G ORNA	ī	PLUG	AND ABANDONME	NT
7	=			5011V6F 511V6	[]	CASING TEST AND C	_	╡	, 202 /		
PULL OR ALTER CASING				CHANGE PLANS	السا		porary #	_ _=	abandor	1	X
					[]	OTHER LEN	apor ary p	-	abanco.		<u> — Lii</u>
OTHER											
17. Describe Proposed or C	omplet	ted Operation	s (Clear	rlv state all pert	inent det	ails, and give perting	ent dates, inc	luding e	stimated date of	starting any pr	oposed
work) SEE RULE 1105		,ou operation	-,	,					•		•
7-6-69											
Pull rods	and	tubing.	remo	ove surfac	e equi	ipments.					
Casing le	fr 1	n the ho	10 ta	ith can so	rewed	on the top of	of casing	for	protection	a.	
Casing le	F F 71	ii che no	TE W	ich cap ac	LCMCG	on one cop c	J. U UUZII.E	,	process		
18. I hereby certify that the	inform	nation above	is true	and complete to	the best	of my knowledge and	l belief.				
	-										
SIGNED CLIFTE TI	77.	tomera	/	T 11	rle C	eologist			DATE 7-2	3-69	
											
1,	1/1			, */	a	eologist NL AND GAS (NS)	PECTOŘ		All	G 5 - 191	Ce
APPROVED BY	14	LIVE	asl	TIT TIT	rle				DATE TO	4 0 19 1) y —

CONDITIONS OF APPROVAL, IF ANY: