

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Copy 3.
SUBMIT IN (Other instr. on reverse side) LICATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NA-07390-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson Federal "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Boothman Area Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**Sec. 30 (SE/4 SW/4),
T-10-S, R-26-E, NMPM**

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shell Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1858, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**330' FSL & 1680' FWL (SE/4 SW/4), Sec. 30,
T-10-S, R-26-E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3782' dr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

**Spudded at 10:00 A.M. (MST), September 5, 1964
Ran 157' of 9 5/8" (32.3#, H-40) casing and cemented at 167'
with 75 sacks Incor plus 3% CaCl₂. Plug down at 4:00 P.M. (MST),
September 5, 1964. Cement did not circulate. After WOC 9 1/2 hours,
tested casing to 600 psi for 30 minutes - no pressure drop.**


Option Two:

- 1. 88.5 cubic feet**
- 2. 75 sacks Lone Star Incor plus 3 sacks Anhydrous Calcium Chloride**
- 3. 60° F.**
- 4. 62° F.**
- 5. 500 psi**

RECEIVED

SEP 18 1964

**D. C. C.
ARTESIAL OFFICE**



**RECEIVED
SEP 16 1964
U. S. GEOLOGICAL SURVEY,
ROSWELL, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By
R. J. Doubek

TITLE Division Mechanical Engineer DATE September 14, 1964

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.