Form 9-881 a (Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

30-005-10137 APR - 7 1964
TS ON WELL

SUNDRY NOTICES	AND	REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) April 23 , 19 64 England Federal Well No. 2 is located 1980 ft. from | N | line and 660 ft. from | E | line of sec. 30 NMPM ECEIVED

(State or Territory)

APR 3 0 1964 Linda San Andres The elevation of the derrick floor above sea level is ft.

We propose to drill to a total depth of approximately 1200 feet with cable tools and complete in the San Andres formation. The casing program will be as follows: 8 5/8-inch 36#, J-55 surface casing to be set at 100 feet and cemented with 75 sacks. Cement will be circulated to surface. 4 1/2-inch 9.6#, J-55 casing set at 1200 feet and cemented with 100 sacks cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before open Company Ray Smith Address Box 953, Midland, Texas Title ____Agent