

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Socony Mobil Oil Company, Inc. ✓		8. Farm or Lease Name C. L. O'Brien "D"
3. Address of Operator Box 1800, Hobbs, New Mexico		9. Well No. 1
4. Location of Well UNIT LETTER "1" , 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 9S RANGE 28E NMPM.		10. Field and Pool, or Wildcat Undesignated WC
15. Elevation (Show whether DF, RT, GR, etc.) GR 3949		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2675 TD - 2670' PBTD

Attempted to complete well in San Andres (2575-2593) Swab test 100% water.  
Propose to plug and abandon well. Spot 25 sx cement plug across perfs. 2575-2593.  
Spot 20 sx cement plug @ 400' (top of cement) to protect fresh water sands. Spot  
5 sx cement plug at surface. Erect marker monument with proper markings. 10# of  
mud will be left between all plugs. Call NMOC at Artesia for inspection after  
location is cleaned.

Note: This will confirm verbal approval with Mr. Armstrong, Artesia, New Mexico,  
January 15, 1965.

RECEIVED

JAN 19 1965

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. J. McDaniel TITLE Group Supervisor DATE 1-16-65

APPROVED BY M. L. Armstrong TITLE Oil and Gas Inspector DATE JAN 19 1965

CONDITIONS OF APPROVAL, IF ANY: