Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department



DISTRICTI

OIL CONSERVATION DIVISION

Form C-103 Revised 1-1-89

P.O. Box 1980, Hobbs, NM 8824	2040 Pacheco St.					WELL API NO.				
DISTRICTIO		Santa Fe, NM 87505					30-005- 1-140 /0/40			
P.O. Drawer DD, Artesia, NM 882	210					sindicate	Type of Lea	(T- ·-	1	\
DISTRICTIII 1000 Rio Brazos Rd., Aztec, NM	87410					∘State Oil	& Gas Lea	STATE se No.) FEE	X
TOO THE DIGITOS RU., MAREL, NM	U/41U									
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C 101) FOR GIGH PROPOSALS.)										
							rt-ease Name or Unit Agreement Name Twin Lakes San Andres Unit			
(FORM C-101) FOR SUCH PROPOSALS.)										
OL GAS WELL OTHER										
₃Name of Operator Hanagan Petroleum Corporation							₃Well No. 53			
₃Address of Operator P.O. Box 1737 Roswell, N.M. 88202							Pool name or Wildcat Twin Lakes San Andres (Assoc.)			
4Well Location	, , , , , , , , , , , , , , , , , , , ,) WIII L	akes Gai	Mules (As	soc.)	
Unit Letter A	660 F	el From The	North		Line and66	0 Feet	From The	East	Line	
Section	2	Township	98		Range 28E	NMPM		Chaves	County	
		∷ccio] ⊲eElevation (Si	how whether	DF, I	RKB, RT, GR, etc.)					
¹¹ C	heck App	ropriate Box to	Indicate	Na	ture of Notice, F	Report or	Other F	Data		
		ENTION TO:			1	•		EPORT OF	·	
PERFORM REMEDIAL WORK		PLUG AND ABANI	DON 5	\	REMEDIAL WORK			ALTERING CA		[]
TEMPORARILY ABANDON		CHANGE PLANS	r F	7	COMMENCE DRILLIN	G OPNS		PLUG AND AN		l, l 1 - 1 1 1 1 1 1 1 1 1 1 1
PULL OR ALTER CASING			L		CASING TEST AND C			. LOGINGIA	C II ALVOI WELL IV	" L.J
OTHER:			Γ	-]	OTHER:		لــا			J 7
12Describe Proposed or Complete	d Operations (Clearly state all nortinen	t details and	aive		n estimated data	of etarting	any proposed		_ Ll
work) SEE RULE 1103.	op oremona (C	any maio un pointelle	. aviana, anu	3110	poningin uaros, menulin	у өмпикей ОНГ	ਾ staRING	апу ргорозеа		
Notify NMOCD - Artesia,		to commencemen	t of proced	lure						
2447 1. Set CIBP @ 2 550	. *	-	2542		e*	123	;5670			
RIH circlate well w/	9.8# mud	inic (TOP perise)	2.3 00)				4	970		
 cut & pull 4 1/2 @ RIH spot 100' plug 	2000' 50' in 50' ou	t cut wor tan Min	. 2(cx 10	men	of Place	7.0	- 4 1 ? •••			
5. spot 160' cmt from	160 to surfac	ce		, ; ()	· • • • • • • • • • • • • • • • • • • •	RECE	12.79	213		
6. cut off well head sel	. dry hole ma	rker & clean location	on			OCD - AR	VED	114		
						- 11	'ESIA	15/		
							do.	,V)''		
						OCD - AR	0.00	/		
* Notific NM	1, O. C. D.	to witness Pl	UCCIRC 6	pe.						
* Notific N.M. I hereby certify that the information			est of my know	lede	ge and belief					
SIGNATURE Wayne &	Brooks			TITL	_agent			DATE 07-0	6-99	
TYPE OR PRINT NAME: Wayne Brooks							-	TELEPHONE NO.	915 -684889	90
(This space for State Use)										
APPROVED BY THIS (S.C.	receptell			-C	e Field Dan	π		DATE 8/	10/00	
CONDITIONS OF APPROVAL, IF ANY	mapeu		 -	1111	F Field Rep.	<u>+-</u>		DATE 0/	12/71.	