NO. OF COPIES RECEIVED	D =	Form C-103
DISTRIBUTION	RECEIVE	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	Crn a	
U.S.G.S.	SEP 2 9 1970	5a. Indicate Type of Lease
LAND OFFICE	1070	State Fee X
OPERATOR /	) n -	5, State Oil & Gas Lease No.
	ARTESIA. C.	
SHINDRY	NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPE	NOTICES AND REPORTS ON WELLS  DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  N FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.	The state of the s	7. Unit Agreement Name
OIL GAS WELL	OTHER. Saltwater Disposal	
		8. Farm or Lease Name
Robert Klabzuba, Munson & Seaman		White
3. Address of Operator		9. Well No.
		1 , )
1209 Birch, Hurst, Texas 76053		2(SWD)
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER		Racetrack San Andres
THE West LINE. SECTION	18 TOWNSHIP 10-S RANGE 28-E NMPM.	
	15, Elevation (Show whether DF, RT, GR, etc.)	12. County
	3761 DF	Chaves ()
16. Check As	ppropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:		
NOTICE OF INT	308320021	REPORT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	1 of Will T for moth
	Tower flow Est Flor	enliase
OTHER	Jas to he little	millase
17 Describe Proposed or Completed Oper	rations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	tations forcers, dende was personally actioned, and give personally access, one small,	estimated date of stating any proposed
7-17-70 Rods and tubing	were pulled and the tubing rerun with a 4 1/2"	Baker Model "A" tension
	42' D.F. Perforations below packer for water of	
	Perforations above packer for gas production 23	
7-18-70 Acidized perform	tions 2252' - 2269' and 2283' - 2289' with 1000	) gallons of 15%
regular acid. Max. pressure 1130 p.s.i. @ 2.2 bbls. per min. Well on vacuum		
	ax. pressure rigo pasara o zaz borsa per mina	ACTI OII VOCUUM
in 15 min.		
0 ) 70 77 22 4 31		
8-4-70 Well taking wate	r on a vacuum.	
10.71	have in two and complete to the host of my brand-d and ballet	
18. I nereby certify that the information a	bove is true and complete to the best of my knowledge and belief.	
$\mathcal{I} \mathcal{I} \mathcal{I} \mathcal{I} \mathcal{I} \mathcal{I} \mathcal{I} \mathcal{I} $	Paff Namt	Sant 00 1070
SIGNED OLT !!	Agent Agent	Sept. 22, 1970
2121		OCT 1 1970
(1) (1 /10	OH AND ONE INSPECTOR	101 M