

406-262-9960

FAX COVER SHEET

OIL CONSERVATION DIVISION
1301 W. GRAND AVE
ARTESIA, NM 88210

PHONE (505-748-1283
FAX (505-748-9720

Date 12-14-01

TO: Cole Chandler

FROM: GERRY GUYE

NUMBER OF PAGES 2 (INCLUDING COVER SHEET)

MESSAGE Maybe this will help - any Questions please Call.


Operator Klabzuba Oil Inc
 Well White #2
 Unit N Section 18 Township
 API # 30-005 - 10165

TOPS

10 Range

28

Yates @ 413'



- * Contact OCD 24 hrs. prior to any work done.
- * Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- * Install dry hole marker as per Rule 202.B.2
- * Plugs are to be set from point indicated up.
- * Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- * Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- * Surface plug will be from 0' - 60'
- * Where plugs are required, cement must be placed inside and outside of **all** casing string(s) in the correct footage or sacks required, if **no cement exists**.
- * Plugs to be tagged will be indicated.