

RECEIVED
OCD - ARTESIAN

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

5. Lease Designation and Serial No.
NMLC068127

6. If Indian, Allottee of Tribe Name

7. If Unit or CA/Agreement Name and/or No.

Federal

8. Well Name and No.

001

9. API Well No.

30-005-10170

10. Field and Pool, or Exploratory Area

Linda San Andres

11. County or Parish, State

Chaves, NM

Unit Letter N - Sec 33-06S-26E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug & Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on the file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CASING
95/8 100' 90'
4 1/2 1075
press 1000-35

MIRU BUSU, pull production exp. Pump sand across
perfs to 950', dump bail 35' cmt, displace hole
w/ Gelled Brine. Perf @ 140' pump 100' cmt plug
Pull out of hole & pump 88' surface plug. Install

dry hole marker & clean location
Place 100' cmt plug on top of sand & Tag
Place 100' cmt. plug @ 950' - 850'
Perf @ 140' & 88' to surf. Set plug from 140' to surf.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Russell Whited

Signature

Title

Owner - Operator

Date

01-26-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

R. E.

R. E.

1/29/02

is not warrant or certify that the
which would entitle the

Office

RFO

Co
api
api

Accepted for record

only FEB 5 2002