

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)August 31, 1985
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. LEASE DESIGNATION AND SERIAL NO. NM 022584	
2. NAME OF OPERATOR Stevens Operating Corporation		3. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A	
3. ADDRESS OF OPERATOR P. O. Box 2203 Roswell, NM 88201		4. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements. See also space 17 below.) At surface 990 FSL, 330 FEL, Sec. 29, T-7-S, R-26-E		5. FARM OR LEASE NAME Sun Federal	
5. PERMIT NO.		6. WELL NO. 1	
6. ELEVATIONS (Show whether of, RT, or, etc.) 3665.7 GR		7. FIELD AND POOL, OR WILDCAT Pecos San Andres	
7. COUNTY OR PARISH Chaves		8. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-7-S, R-26-E	
8. STATE NM		9. COUNTY OR PARISH Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

CHANGE PLANS

☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☒

(Other)

☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-2-85

- Set CIBP @ 1110' + 35' cement cap.
- Find Free Point of 4 1/2 csg @ 400'.
- Perforate 4 1/2 csg @ 400'. Pump 160 sxs class "C" + 2% CaCl₂ to circ cement to surface outside 4 1/2 csg & leave cement inside 4 1/2 csg to surface.
- Set Dry Hole Marker.

Post FD-2
2-1-85
PVA

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Controller

DATE 1-3-85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
PETER W. CHESTER

FEB 4 1985

BUREAU OF LAND MANAGEMENT
ROSSELL RESOURCE AREA

