

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Co.
N.M. DIV-Dist. 2

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

1301 W. Grand Avenue
Artesia, NM 88210

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

3a. Address *MEW Enterprise*
300 S. Kentucky
Roswell, N.M. 88201

3b. Phone No. (include area code)
505/262-0020

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

G - Sec 26 - 07S - 26E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

Date Federal

8. Well Name and No.

9

9. API Well No.

30-005-10227

10. Field and Pool, or Exploratory Area

Leslie Springs

11. County or Parish, State

Chavez N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☒ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

*4-15-02 MIEU Well, Pooty production equipment, Rig up wellhead
peet @ 950', Dump sand. TTH Tag at 1387' mix & pump 75's cmt, pull up hole & clear
hole w/ gelled Brine, mix & pump 285's cmt in peets @ 950' Last cmt in 4 1/2 to 850'
Pooty SI. 3-16-02 Trip in hole Tag cmt @ 837' start out of hole Brake DN.
4-18-02 Finish Trip out of hole peet at 150', Trip in & pump 255's cmt, Pooty
to 6' & pump cmt in 4 1/2 to surface, Pooty mix & pump , to Finish out
4 1/2 casing.*

APPROVED

ARMANDO A. LOPEZ
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Signature

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

