

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

DEC - 1 1986
O. C. D.

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator: Brady W. Production, Inc. Co.
Address of Operator: P.O. Box 9128, Midland, Texas 79708
Location of Well:
UNIT LETTER H, 1666.5 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 7S RANGE 26E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name: Sturgeon "A"
9. Well No.: 1
10. Field and Pool, or Wildcat: Linda San Andres

13. Elevation (Show whether DF, RT, GR, etc.)
GR, 3594.1

12. County: Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

<p>REPAIR REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>WELL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
---	--	---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

We propose to plug and abandon this well on or about the 8th. day of December, 1986, with a 25 sx. plug placed from 670' to 1031' T.D. and a 10 sx. plug from surface to 145'. 10# bentonite mud to be placed between cement plugs from 145' to 670'. A 4" marker to be placed in top of well. All casings to be left in hole.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Brady TITLE President DATE Nov. 26, 1986

PROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE DEC 04 1986

CONDITIONS OF APPROVAL, IF ANY:

Plugging